



Inspection Report (Rough Terrain Crane)

General Info

| | |
|--|--|
| B&B Stock Number | A8659042 |
| Year | 2010 |
| Make | Link-belt |
| Model | RTC 8050 |
| Serial Number | J6K0-1746 |
| Serial Plate Photo |  |
| Hour Meter Reading | 3390.2 |
| Hour Meter Photo |  |
| Previous Application (e.g., earth moving, mining, demolition, etc) | Sanitation district |



Features and Configuration

Inspection Report (Rough Terrain Crane)

| | |
|-------------------------------------|-----------------------|
| Travel System | Wheels & Tires |
| Heat | Yes |
| A/C | Yes |
| Radio | No |
| Backup Camera | No |
| Telematics | No |
| Load Movement Indicator (LMI) | Yes |
| LMI Make/Model | Greer company |
| Boom Type | Hydraulic Telescoping |
| Jib? | Yes |
| Jib Length (ft and inches) | 28.5'-51' |
| Crane Capacity (tn) | 50tn |
| Max Reach (ft and inches) | 110' |
| Max Elevating Angle (degrees) | 78 degrees |
| # Boom Sections | 3 |
| Winch System | Braden |
| Cable Size | Unable to verify |
| Compression Brake | Unable to verify |
| Load Blocking System | Unable to verify |
| Outriggers | Yes |
| OMM (Operator & Maintenance Manual) | Yes |

OMM Specifications

OMM Specifications









| | |
|-----------------------|--|
| Detail Specifications | Take photos of the detailed spec pages included in the operator's manual |
| OMM Spec Photos |  |
| |  |

Inspection Report (Rough Terrain Crane)

Exterior 360 Walkaround

360 Walkaround & Operating Video































Walkaround Photos & Operating Video

| | | | | | |
|----------------------------|---|---|--|---|---|
| Exterior Walkaround Photos |  |  |  |  |  |
| |  |  |  | | |
| Operating Video | Click to Download | | | | |
| Additional Video | Click to Download | | | | |
| Additional Video | Click to Download | | | | |


General Appearance Inspection Points

General Appearance

General Appearance Photos

| | | | | | |
|--------------------------|---|---|--|---|---|
| Close-up Exterior Photos |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |

Inspection Report (Rough Terrain Crane)



General Appearance Inspection Points

| Inspection Rating Criteria | Rating Scale | Explanation |
|----------------------------|--|---|
| | 1 - Service Required | Requires immediate repairs to function as expected. |
| | 2 - Above Average Wear & Tear | Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed. |
| | 3 - Normal Wear & Tear | Exhibits wear that is consistent with age and usage. Operation is normal, and as expected. |
| | 4 - Very Light or Minimal Wear | Exhibits very minimal wear. Operation is better than expected given age and usage. |
| | 5 - Like New, Recently Replaced | Excellent condition, free of visible wear or damage. Operation is within factory specifications. |
| Body Panels | 3 - Normal Wear & Tear | |
| Body Panel Condition | Visible chipped paint or dents | |
| Doors / Canopy Latches | 3 - Normal Wear & Tear | |
| Steps / Ladders | 3 - Normal Wear & Tear | |
| Handrails | 3 - Normal Wear & Tear | |
| Glass | 3 - Normal Wear & Tear | |
| Mirrors | 3 - Normal Wear & Tear | |
| Exterior Lights | 3 - Normal Wear & Tear | |
| Overall Exterior | 3 - Normal Wear & Tear | |
| Comments | Normal wear and tear no major issues to report | |







Control Station Inspection Points

Control Station


Control Station Photos



Inspection Report (Rough Terrain Crane)

| | |
|---------------------------------------|--|
| |  |
| |  |
| |  |
| |  |
| |  |
| |  |
| Control Station Type | Enclosed Cab (EROPS) |
| Control Type | Pilot Controls |
| Control Configuration | N/A |
| Seat | 3 - Normal Wear & Tear |
| Cabin Lights | 0 |
| Safety Lock Out / Stop | 3 - Normal Wear & Tear |
| Controls & Switches | 3 - Normal Wear & Tear |
| Hour Meter Activity | 3 - Normal Wear & Tear |
| Other Gauge Activity | 3 - Normal Wear & Tear |
| Heater & A/C | 3 - Normal Wear & Tear |
| Travel Alarm | 0 |
| Horn | 3 - Normal Wear & Tear |
| Backup Camera | 0 |
| Control Station Overall Rating | 3 - Normal Wear & Tear |
| Anti Two Block System | 0 |

















Inspection Report (Rough Terrain Crane)

| | |
|--------------------------------------|--|
| Load Movement Indicator (LMI) | 3 - Normal Wear & Tear |
| Load Movement Indicator (LMI) Photos |  |

Engine Inspection Points

Engine

Engine Compartment Photos

| | | | | | |
|--|---|---|--|---|---|
| Engine Data Plate |  | | | | |
| Engine Compartment Photos |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |
| Engine Type (Make, Model, Cylinders, Hp) | Cat, c6.6 | | | | |
| Emissions Tier | Tier 3 | | | | |
| Engine Serial Number | Unable to verify | | | | |

Inspection Report (Rough Terrain Crane)

| | |
|--|--|
| Engine Fuel Type | Diesel |
| Blow-by (Visual Observation Check) | No |
| Unusual Noises (Upon Start-up, Idle, Shutdown) | No |
| Engine Smoke (Upon Start-up, Idle, Shutdown) | No |
| Engine Exhaust Color | Clear |
| Battery | 3 - Normal Wear & Tear |
| Radiator | 3 - Normal Wear & Tear |
| Belts | 3 - Normal Wear & Tear |
| Hoses | 3 - Normal Wear & Tear |
| Water Pump | 3 - Normal Wear & Tear |
| Cooling System Leaks | No |
| Coolant Appearance | 3 - Normal Wear & Tear |
| Oil Leaks | No |
| Oil Appearance | 3 - Normal Wear & Tear |
| Fuel Leaks | No |
| Equipped with DPF (Diesel Particulate Filter) | No |
| Requires DEF (Diesel Exhaust Fluid) | No |
| Overall Engine Rating | 3 - Normal Wear & Tear |
| Overall Engine Appearance | Dusty & dry |
| Overall Engine Comments | Normal wear and tear no major issues to report |

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points

| | | | | | |
|-------------------|--|--|--|--|--|
| Drivetrain Photos |  | | | | |
| | | | | | |
| | | | | | |

Inspection Report (Rough Terrain Crane)

| | |
|---------------------------------------|---|
| Hydrostatic Transmission? | No |
| Transmission Info (Make/Model/Speeds) | Spicer/ 3. 5HR3261-032(model)/ MBEA 350871(serial) |
| Drive Type | 4WD |
| Transmission Components | 3 - Normal Wear & Tear |
| Parking Brake | 3 - Normal Wear & Tear |
| Overall Drivetrain Rating | 3 - Normal Wear & Tear |
| Overall Drivetrain Comments | Normal wear and tear no major issues to report |

Chassis Photos

| | | | | | |
|----------------|---|---|--|---|---|
| Chassis Photos |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  | | | |

Chassis Inspection Points

| | |
|-------------------|------------------------|
| Frame | 3 - Normal Wear & Tear |
| Stance | 3 - Normal Wear & Tear |
| Turntable Bearing | 3 - Normal Wear & Tear |
| Front Axle | 3 - Normal Wear & Tear |
| Rear Axle | 3 - Normal Wear & Tear |
| Outriggers | 3 - Normal Wear & Tear |
| Outrigger Pads | 3 - Normal Wear & Tear |
| Overall Chassis | 3 - Normal Wear & Tear |





Wheels & Tires

Wheels & Tires

Wheels & Tires Inspection Points

| | |
|------------------|-----------|
| Wheel Type | Pneumatic |
| Wheel Seal Leaks | No |

Inspection Report (Rough Terrain Crane)

| | |
|------------------------------------|---|
| Tire Brand | Maxam |
| Tire Size | 23.5r25 |
| Front Left Tire - Ratio Remaining | 70% |
| Front Left Tire Photos |  |
| Front Right Tire - Ratio Remaining | 70% |
| Front Right Tire Photos |  |
| Rear Right Tire - Ratio Remaining | 70% |
| Rear Right Tire Photos |  |
| Rear Left Tire - Ratio Remaining | 70% |
| Rear Left Tire Photos |  |
| Wheels & Hubs | 3 - Normal Wear & Tear |

Track Undercarriage Components

Undercarriage Inspection Points

Basic Information

| | |
|---|-----|
| High Drive Configuration | N/A |
| Sealed and Lubricated Track Undercarriage (SALT)? | N/A |
| Oil Filled? | N/A |
| Grease Filled? | N/A |
| Track Shoe Width (inches) | N/a |

Undercarriage Inspection Points

| | |
|------------------------|---|
| Sprocket Teeth | 0 |
| Track Bushings | 0 |
| Track Frames | 0 |
| Pivot Shafts | 0 |
| Equalizer Bar & Joints | 0 |
| Front Idler | 0 |


Inspection Report (Rough Terrain Crane)

| | |
|--------------------------------|-----|
| Track Tensioner | 0 |
| Track links | 0 |
| Bottom Rollers | 0 |
| Carrier Rollers | 0 |
| Overall Undercarriage | 0 |
| Overall Percent Estimate | N/A |
| Overall Undercarriage Comments | N/A |

Hydraulics Overall Inspection Points


Hydraulics Overall

Hydraulic System Inspection Points


| | |
|--|---|
| Hydraulic System Photos |  |
| Wet or Damp Hydraulic Lines / Fittings | Yes |
| Hydraulic Lines/Fittings | 2 - Above Average Wear & Tear |
| Hydraulic Lines / Fittings Condition | Dried seepages observed, Twisted, kinked, or flattened hydraulic hoses |
| Comments | Hard line to rear right outrigger bent |
| Hydraulic Pump(s) | 3 - Normal Wear & Tear |
| Unusual Noises | No |
| Hydraulic Pump Notes | No unusual noises heard during operation |

Hydraulic Cylinder Inspection Points

Inspection Report (Rough Terrain Crane)

| | |
|---------------------------|--|
| Hydraulic Cylinder Photos |  |
| Mounting Pins | 3 - Normal Wear & Tear |
| Cylinder Oil Leaks | No |
| Hydraulic System Overall | 3 - Normal Wear & Tear |
| Main Hoist | 3 - Normal Wear & Tear |
| Auxiliary Hoist | 3 - Normal Wear & Tear |
| Swing Motor | 3 - Normal Wear & Tear |

Crane Components - Photos

| | |
|------------------------|--|
| Crane Component Photos |  |
|------------------------|--|

Crane Components - Inspection Points

| | |
|----------------------|------------------------|
| Counterweight | 3 - Normal Wear & Tear |
| Boom Angle Indicator | 3 - Normal Wear & Tear |
| Main Boom Sections | 3 - Normal Wear & Tear |
| Main Boom Pins | 3 - Normal Wear & Tear |
| Boom Head Section | 3 - Normal Wear & Tear |
| Wear Pads | 3 - Normal Wear & Tear |
| Jib | 3 - Normal Wear & Tear |
| Fairlead | 3 - Normal Wear & Tear |

Inspection Report (Rough Terrain Crane)

| | |
|--------------------------|------------------------|
| Sheaves | 3 - Normal Wear & Tear |
| Main Load Block | 3 - Normal Wear & Tear |
| Overhaul Ball | 3 - Normal Wear & Tear |
| Crane Components Overall | 3 - Normal Wear & Tear |

Functional Test

Functionality Assessment

Functionality Assessment

| | |
|-----------------------------------|--|
| Engine | 3 - Normal Wear & Tear |
| Transmission/Drivetrain | 3 - Normal Wear & Tear |
| Travel (Forward/Reverse/Steering) | 3 - Normal Wear & Tear |
| Brakes | 3 - Normal Wear & Tear |
| Hydraulic System | 3 - Normal Wear & Tear |
| Electric Operating System | 3 - Normal Wear & Tear |
| Controls | 3 - Normal Wear & Tear |
| Safety Systems | 3 - Normal Wear & Tear |
| Core Functions | 3 - Normal Wear & Tear |
| Attachments | 3 - Normal Wear & Tear |
| Overall Functional Test Comments | Normal wear and tear no major issues to report |

Overall Assessment

Overall Assessment

| Inspection Rating Criteria | Rating Scale | Explanation |
|----------------------------|---------------------------------|---|
| | 1 - Service Required | Requires immediate repairs to function as expected. |
| | 2 - Above Average Wear & Tear | Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed. |
| | 3 - Normal Wear & Tear | Exhibits wear that is consistent with age and usage. Operation is normal, and as expected. |
| | 4 - Very Light or Minimal Wear | Exhibits very minimal wear. Operation is better than expected given age and usage. |
| | 5 - Like New, Recently Replaced | Excellent condition, free of visible wear or damage. Operation is within factory specifications. |
| Exterior Rating | 3 - Normal Wear & Tear | |
| Interior Rating | 3 - Normal Wear & Tear | |
| Safety Rating | 3 - Normal Wear & Tear | |
| Quality Rating | 3 - Normal Wear & Tear | |
| Functionality Rating | 3 - Normal Wear & Tear | |
| Overall Rating | 3 - Normal Wear & Tear | |

Inspection Report (Rough Terrain Crane)

| | |
|--------------------------------|---|
| Summary Video | Click to Download |
| What's Great About the Machine | The great thing about this machine is that it starts right up with no abnormal noises heard as well as no abnormal noises heard while function testing the machine. |
| What Needs Work | The things that need work on this machine are the bent hard line to the rear right outrigger and the areas of dry seepage found around main swivel components |
| Date/Time | 04-18-2024 |
| Inspector Name | Javier Bocanegra |