



## Inspection Report (Skip Loader)

### General Info

B&B Stock Number	A2101830
Year	1994
Make	Case
Model	480F LL
Serial Number	JJG0006140
Serial Plate Photo	
Hour Meter Reading	5535.2
Hour Meter Photo	
Previous Application (e.g., earth moving, mining, demolition, etc)	Sanitation district

### Features and Configuration

Bucket	Yes
Bucket Specs	6' 10"
Box Blade	Yes
Box Blade Specs	7'
Additional Attachment(s)?	No
Auxiliary Hydraulics	No
Heat	No









## Inspection Report (Skip Loader)

A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

### Exterior 360 Walkaround

### 360 Walkaround & Operating Video

### Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	  
Operating Video	<a href="#">Click to Download</a>
Additional Video	<a href="#">Click to Download</a>
Additional Video	<a href="#">Click to Download</a>

### General Appearance Inspection Points

### General Appearance

### General Appearance Photos

Close-up Exterior Photos	    
	    
	    
	  

### General Appearance Inspection Points





















## Inspection Report (Skip Loader)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	2 - Above Average Wear & Tear	
Body Panel Condition	Areas of surface rust observed, Visible chipped paint or dents	
Comments	Missing engine panel right side, paint chips and surface rust throughout exterior of machine	
Doors / Canopy Latches	0	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	3 - Normal Wear & Tear	
Glass	0	
Mirrors	3 - Normal Wear & Tear	
Exterior Lights	3 - Normal Wear & Tear	
Overall Exterior	2 - Above Average Wear & Tear	
Comments	Paint chips and surface rust visible throughout exterior of machine, missing engine panel right side	

## Control Station Inspection Points


### Control Station

### Control Station Photos

Control Station Photos					
					
					
					



## Inspection Report (Skip Loader)

	
Control Station Type	Open Cab (OROPS)
Control Type	Lever Controls
Control Configuration	N/A
Seat	4 - Very Light or Minimal Wear
Seat Condition	Seat(s) in good condition, no stains or tears in upholstery, Seat belt secures properly
Cabin Lights	0
Safety Lock Out / Stop	0
Controls & Switches	2 - Above Average Wear & Tear
Controls & Switches Condition	Other (see comments)
Comments	Loose levers
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	0
Travel Alarm	0
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Control Station Overall Rating	2 - Above Average Wear & Tear
Control Station Overall Condition	Significant wear and tear to cabin floor, panels, and ceiling






### Engine Inspection Points

#### Engine

#### Engine Compartment Photos



## Inspection Report (Skip Loader)

Engine Data Plate					
Engine Compartment Photos					
					
					
					
Engine Type (Make, Model, Cylinders, Hp)	Case, 4-390,				
Emissions Tier	Undetermined				
Engine Serial Number	44840427				
Engine Fuel Type	Diesel				
Blow-by (Visual Observation Check)	No				
Unusual Noises (Upon Start-up, Idle, Shutdown)	No				
Engine Smoke (Upon Start-up, Idle, Shutdown)	No				
Engine Exhaust Color	Clear				
Battery	3 - Normal Wear & Tear				
Battery Condition	Clean & dry appearance, tight connections				
Radiator	3 - Normal Wear & Tear				
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks				

## Inspection Report (Skip Loader)

Belts	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Water Pump	3 - Normal Wear & Tear
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Areas of dry seepage at top of engine, missing engine, cover panel right side

## Drivetrain Inspection Points


### Drivetrain

## Drivetrain Inspection Points

Drivetrain Photos					
Hydrostatic Transmission?	No				
Drive Type	4WD				
Transmission Components	2 - Above Average Wear & Tear				
Transmission Condition	Other (see comments)				
Comments	dried seepage found around transmission components				
Parking Brake	2 - Above Average Wear & Tear				
Overall Drivetrain Rating	2 - Above Average Wear & Tear				
Overall Drivetrain Comments	Dried seepage found around transmission components				

## Chassis Inspection Points

## Inspection Report (Skip Loader)

Chassis Photos	
Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Front Axle	3 - Normal Wear & Tear
Rear Axle	3 - Normal Wear & Tear
Oscillating Pin	0
Lift Arm	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Tilt Linkage	3 - Normal Wear & Tear
Tilt Linkage Pins & Bushings	2 - Above Average Wear & Tear
Comments	Component slop noticed due to worn bushings
Bucket to Arm Pins	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear, and tear with some noticeable component slop due to worn bushings

## Wheels & Tires Inspection Points





### Wheels & Tires

## Wheels & Tires Inspection Points

Wheel Type	Pneumatic
------------	-----------



## Inspection Report (Skip Loader)

Wheel Seal Leaks	No
Tire Brand	Firestone
Tire Size	12-16.5(front) 17.5L -24
Front Left Tire - Ratio Remaining	10%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	10%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	10%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	10%
Rear Left Tire Photos	
Wheels & Hubs	3 - Normal Wear & Tear

## Hydraulics Overall Inspection Points

### Hydraulics Overall


### Hydraulic System Inspection Points

Hydraulic System Photos	
-------------------------	--

## Inspection Report (Skip Loader)

Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

## Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear

## Box Blade & Scarifier Inspection Points

Loader Bucket	2 - Above Average Wear & Tear
Bucket Edge / Deflectors	2 - Above Average Wear & Tear
Gannon Box	3 - Normal Wear & Tear
Blade	2 - Above Average Wear & Tear
Comments	Bent blade and missing hardware
Scarifier	2 - Above Average Wear & Tear
Comments	One missing shank, and one missing tooth

## Functional Test

### Functionality Assessment

### Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	2 - Above Average Wear & Tear
Comments	Worn out breaks

## Inspection Report (Skip Loader)

Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	2 - Above Average Wear & Tear
Comments	Sloppy controls
Safety Systems	2 - Above Average Wear & Tear
Comments	Worn brakes
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Above average wear and tear control levers, worn out brakes, Shift lever loose

## Overall Assessment

### Overall Assessment

Inspection Rating Criteria	<b>Rating Scale</b>	<b>Explanation</b>
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	2 - Above Average Wear & Tear	
Interior Rating	2 - Above Average Wear & Tear	
Safety Rating	2 - Above Average Wear & Tear	
Quality Rating	2 - Above Average Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	2 - Above Average Wear & Tear	
Summary Video	<a href="#">Click to Download</a>	
What's Great About the Machine	The thing that is great about this machine is that it starts right up with no abnormal noises heard	
What Needs Work	The things that need work are dried seepage found throughout engine compartment, Loose/sloppy control and worn out brakes	
Date/Time	04-16-2024	
Inspector Name	Javier Bocanegra	