

Inspection Report (Wheel Loader)

General Info

General Info		
B&B Stock Number	A5756739	
Year	2005	
Make	Caterpillar	
Model	966F	
Serial Number	4YG75001	
Serial Plate Photo	CATERPILLAR CERTIFIED 4/TU /5001 AL FUTURE DEPATIFICATION OP THIS UNIT TO CATERPILLAR SHOULD BE REFERENCED BY NUMBER DISPLAYED AT TOP OF THIS PLATE THIS MACHINE REMANUFACTURED BY IN CONFORMITY WITH THE CATERPILLAR CERTIFIED REBUILD PROCESS PRODUCT DENTIFICATION NUMBER CATERPILLAR CATERPILLAR CATERPILLAR SHOULD BE SH-5034	
Hour Meter Reading	8311	
Single Photo	302-5812 HOURS CAT®	
Previous Application (e.g., earth moving, mining, demolition, etc)	Sanitation district	

Features and Configuration

T Catal Co and Comigaration	
Bucket	Yes
Auxiliary Hydraulics	Yes
Quick Coupler	Yes
Heat	Yes
A/C	Yes
Radio	No
Backup Camera	No



Inspection Report (Wheel Loader)

OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	
Operating Video	Click to Download
Additional Video	Click to Download

General Appearance Inspection Points

General Appearance

General Appearance Photos

General Appearance	110.000
Close-up Exterior Photos	
	CAT



Inspection Report (Wheel Loader)



General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation	
	1 - Service Required	Requires immediate repairs to function as expected.	
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	
Body Panels	2 - Above Average Wear &	Tear	
Body Panel Condition	Visible chipped paint or de	nts, Large dents or cracks, A	Areas of surface rust observed
Doors / Canopy Latches	2 - Above Average Wear &	Tear	
Doors / Canopy Latches Condition	Intermittent sticking observ	red on one or more latches/d	loors
Steps / Ladders	2 - Above Average Wear &	Tear	
Steps / Ladders Condition	Bent or broken steps or rur	ngs	
Handrails	2 - Above Average Wear &	Tear	
Handrails Condition	Bent or broken railings		
Glass	3 - Normal Wear & Tear		
Glass Condition	Glass intact, no visible dan	nage	
Mirrors	2 - Above Average Wear &	Tear	
Mirror Condition	One or more mirrors are br	oken or missing	
Exterior Lights	3 - Normal Wear & Tear		
Overall Exterior	2 - Above Average Wear &	Tear	
Comments	Above average wear and to exterior of machine	ear to hand rails, steps And	areas of surface rust on

Control Station Inspection Points

Control Station

Control Station Photos



Inspection Report (Wheel Loader)

Control Station Photos			
Control Station Type	Enclosed Cab (EROPS)		
Control Type	Lever Controls		
Control Configuration	N/A		
Seat	2 - Above Average Wear & Tear		
Seat Condition	Seat(s) have minor surface staining or small tears, Seat belt secures properly		
Cabin Lights	3 - Normal Wear & Tear		
Safety Lock Out / Stop	0		
Controls & Switches	2 - Above Average Wear & Tear		
Controls & Switches Condition	Switches have good functionality, minor cosmetic damage observed		
Hour Meter Activity	1 - Service Required		
Hour Meter Condition	Hour meter is unreadable or not functioning		



Inspection Report (Wheel Loader)

Other Gauge Activity	3 - Normal Wear & Tear
Heater & A/C	3 - Normal Wear & Tear
Travel Alarm	0
Horn	1 - Service Required
Horn Condition	Horn installed but functioning improperly
Backup Camera	0
Control Station Overall Rating	2 - Above Average Wear & Tear
Control Station Overall Condition	Significant wear and tear to cabin floor, panels, and ceiling

Engine Inspection Points

Engine

Engine Compartment Pho	otos
Engine Data Plate	
Engine Compartment Photos	
Engine Type (Make, Model, Cylinders, Hp)	Cat , c-10
Emissions Tier	Tier 3



Inspection Report (Wheel Loader)

Engine Serial Number	Unable to verify
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Radiator	3 - Normal Wear & Tear
Belts	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Water Pump	3 - Normal Wear & Tear
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Oil Appearance	3 - Normal Wear & Tear
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	2 - Above Average Wear & Tear
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Dried seepage found throughout engine compartment

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points





Inspection Report (Wheel Loader)

Hydrostatic Transmission?	No
Drive Type	4WD
Transmission Components	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report

Chassis Inspection Points

Chassis Photos	
Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Front Axle Appearance	3 - Normal Wear & Tear
Rear Axle Appearance	3 - Normal Wear & Tear
Articulating Center Pin Appearance	3 - Normal Wear & Tear
Lift Arm	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Tilt Linkage	3 - Normal Wear & Tear
Tilt Linkage Pins and Bushings	3 - Normal Wear & Tear
Quick Coupler	3 - Normal Wear & Tear



Inspection Report (Wheel Loader)

Quick Coupler to Arms Pins	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear

Wheels & Tires Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points

wheels & fires inspection	II Folitis
Wheel Type	Pneumatic
Wheel Seal Leaks	No
Tire Brand	Yokohama
Tire Size	26.5-25
Front Left Tire - Ratio Remaining	30%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	30%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	50%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	50%
Rear Left Tire Photos	
Wheels & Hubs	3 - Normal Wear & Tear

Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos			
		5	



Inspection Report (Wheel Loader)

Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	2 - Above Average Wear & Tear
Hydraulic Lines / Fittings Condition	Dried seepages observed, Worn, cut, or damaged hose covering
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	Yes
Comments	Leaking hydraulic oil from wiper seals
Hydraulic System Overall	2 - Above Average Wear & Tear
Comments	Above average wear and tear due to leaking hydraulic fluid at the wiper seals

Attachment Inspection Points

Attachments

Additional Attachments

Additional Attaonments	
Attachment Type	Bucket
Attachment Make	Cat
Attachment Size / Specs	10'
Attachment Condition	3 - Normal Wear & Tear



Inspection Report (Wheel Loader)

Attachment Photos	

Functional Test

Functionality Assessment

Functionality Assessment

diotoriality Assessment		
Engine	3 - Normal Wear & Tear	
Transmission/Drivetrain	3 - Normal Wear & Tear	
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear	
Brakes	3 - Normal Wear & Tear	
Hydraulic System	2 - Above Average Wear & Tear	
Comments	Leak at wiper seals	
Electric Operating System	2 - Above Average Wear & Tear	
Comments	Exposed wiring at dashboard	
Controls	3 - Normal Wear & Tear	
Safety Systems	3 - Normal Wear & Tear	
Core Functions	3 - Normal Wear & Tear	
Attachments	3 - Normal Wear & Tear	
Overall Functional Test Comments	Normal wear, and tear with leaks at the wiper seals	

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation	
mapagement daming of the mapagement of the mapag	1 - Service Required	Requires immediate repairs to function as expected.	
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	
Exterior Rating	2 - Above Average Wear & Tear		
Interior Rating	2 - Above Average Wear & Tear		
Safety Rating	3 - Normal Wear & Tear		



Inspection Report (Wheel Loader)

Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal Wear & Tear
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	The great thing about this machine is that it starts right up with no abnormal noises heard
What Needs Work	The things that need work on this machine are the bent handrails and the bent steps, the leaks at the wiper seals and the dry seepage found throughout compartment
Date/Time	04-18-2024
Inspector Name	Javier Bocanegra