

Location: Boom and Bucket
Sebring, FL

TRUCK AND EQUIPMENT CONSULTING LLC – SEMI TRUCK / TRACTOR

Date 4/27/2024
 (Y/M/D)
 Inspector S.E.
 Initials

(Basic Information)	
(Make)	Peterbilt
(Model)	379 Ultra Cab Apartment Sleeper tractor
(Serial Number)	1XP5DB9X5TN406576
(Year of Manufacturing)	1996 (Built 9/1995)
(Color)	Red / Gray Deluxe Interior Trim
(Mileage/Hours)	1,398,838.7 Miles
(Engine)	s/n 5EK61814 Caterpillar 3406 14.6L I6 455 Hp TurboD.
(Transmission)	13 Spd Manual Eaton Fuller RTL015610B
(Origin)	TN, USA

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

Specification and Dimensions	
Class Rating/GVWR	GVWR =52,000 lbs Class 8 = 33,001+ lbs
Wheelbase / Cab	340 in Wheelbase (260 in WB = Std Sleeper Cab)
Chassis Weight	23,000 lbs (17,710 lbs =Std Sleeper Cab)
Tire Size	Sumitomo/Linglong/Fortuna 11R 24.5
Front Axle	Front = Dana Spicer = 12,000 lbs
Rear Axle	Rear = 19,000+19,000 lbs Dana Spicer = 38,000 lbs
Rear Ratio	3.70 Rear
Fuel Capacity	2 x 135 gal tanks = Total 270 gal /26 in diameter
DOT	FL Inspected 9/2023
Air Brake/Engine Brake	Yes Air Brake Yes Jake Brake
Other	APARTMENT CAB Bed, Shower, Kitchenette Gas Range, Water tanks Sink, Refrigerator, Microwave, Cabinets, Storage Closets, Window Treatments, Fully Upholstered, JVC Sound System, Cobra CB, 2nd A/C+Heat, Skylight

		(Check List)					(Remarks)
		A	B	C	D	E	
GENERAL APPEARANCE	(General Appearance-Front)	X					Level Stance, Good grille+chrome, Good hood gaps, bumper, No damage
	(General Appearance-Rear)	X					Good appearance 5th Wheel crossmembers+hydraulics, straight panels
	(General Appearance-Right)	X					Good Right Side panel gaps+ fitment No dings or paint cosmetics V.Clean
	(General Appearance-Left)	X					Good Left Side panel gaps+ fitment No dings or paint cosmetics V.Clean
	(General Appearance-Upper)	X					Good appearance upper surfaces, cab roof, hood, 5th wheel deck
	(Major / Minor Surface Rust)	X					Minimal surface rust cosmetics on some lower components covers
	(Body Panels / Covers – Rust Damage / Cancer)	X					No Panel Damage No Rust Damage or Cancer seen
	(Visible Weld Repairs / Stress Cracks)	X					No accident repairs seen 1 Lower Cannister cover has epoxy repair
	(Glass Condition)	X					Good Glass
	(Chassis / Undercarriage Damage)	X					Good appearance frame rails, chassis+crossmembers Dry No damage
OPERATOR'S COCKPIT	(Operator Cabin)	X					Solid Floors, Clean+straight Some minor surface and trim cosmetics
	(Operator Controls and Switches)	X					Complete Good Appearance and Functionality
	(Odometer Activity)	X					Working
	(Other Gauge Activity)	X					Working
	(Door / Canopy Latches)	X					Good function
	(Safety – Horn / First Aid Kit)	X					Working
	(Operator Seat Condition)	X					Both Seats Good Condition
	(Other)	X					A/C + Accessories working
ENGINE	(Oil Color / Fluid Appearance)	X					Good Clean Oil Appearance
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)	X					Easy start No unusual noises Smooth Idle
	(Engine Exhaust Color – White / Blue / Black / Clear)	X					Clear at start up Clear at Operating Temperature
	(Oil Leaks)	X					None seen
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)	X					No smoke issues No Blow By seen
	(Coolant Color / Fluid Appearance)	X					Normal appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)	X					No pump noises No coolant leaks seen
	(Coolant Leaks from Radiator)	X					None seen
	(Overall Engine Appearance Clean / Wet / Dry)	X					Dry appearance No damage or rust seen
	(Other)						

ELECTRICAL	(Lighting System Condition)	X				Working
	(Reverse Alarm / Backup Signal)					No Reverse Alarm No Rear View Camera
	(Battery Condition)	X				Good Appearance
	(Other Electric Device Condition)	X				No loose or dangling wires seen
TIRES DUMP BODY	FRONT TIRES+RIMS	X				Front Tires = B / B+
	REAR TIRES+RIMS X2	X				X2 Mid Axle Tires Good = B / B+
	BACK TIRES+RIMS X2	X				X2 Rear Axle Tires Good = B / B+
	OTHER	X				Hubs Clean+Dry appearance Good Chrome No dings or dents
TRANSMISSION	(Clutch Noise / Function)	X				Good clutch function No noise or chatter
	(Transmission Noise / Function)	X				Good Transmission function Forward and Reverse
	(Shift Lever Condition & Function)	X				Good Shifter function
	(Other Remarks)	X				Good Tranmssion Function
DIFFERENTIAL	(Rear Diff - Noises ?)	X				No Rear Diff Noises heard
B R A K E S	(Foot Brake)	X				Good
	(AIR BRAKE)	X				Working
	(Parking Brake)	X				Good function
OPERATION	FORWARD & REVERSE	X				Good Forward and Reverse
	STEERING + BRAKES	X				Good Steering and Brakes
	ENGINE	X				Engine Good Response
	CONTROLS	X				Controls Good Function and Response
RATINGS	OVERALL VISUAL INSPECTION	X				Good dry appearance engine, chassis+frame crossmembers+components
	COMMENTS	X				Clean+straight body+chrome Apartment has good appearance complete
	OVERALL PERFORMANCE INSPECTION	X				Good Driving Performance Good engine, steering, brakes,forward+reverse
	COMMENTS					Unable to fully test all apartment features+systems for performance

OVERALL EXTERIOR RATING: B QUALITY: B
 OVERALL INTERIOR RATING: B SAFETY: B
 OVERALL PERFORMANCE: B FUNCTIONALITY: B
OVERALL GRADE EVALUATION: B
 FLUID SAMPLE REQUEST (Y/N) n OIL n COOLANT n

TIRES
 *A:Remaining Ratio 90% or more
 *B:Remaining Ratio 70% or more
 *C:Remaining Ratio 50% or more
 *D:Remaining Ratio 20% or more
 *E:Remaining Ratio 20% or less