



Inspection Report (Skid Steer/Track Loader)

General Info

B&B Stock Number	A5067887
Year	2018
Make	Caterpillar
Model	249D
Serial Number	CAT0249DEGWR02723
Serial Plate Photo	
Hour Meter Reading	740.8
Hour Meter Photo	
Previous Application (e.g., earth moving, mining, demolition, etc)	Construction

Features and Configuration


Travel System	Track Undercarriage
Bucket	Yes
Bucket Specs	66"
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
High Flow	No
Heat	No

Inspection Report (Skid Steer/Track Loader)

A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No

OMM Specifications

OMM Specifications

Detail Specifications	Take photos of the detailed spec pages included in the operator's manual
OMM Spec Photos	

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	
Operating Video	Click to Download

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos	
--------------------------	--

Inspection Report (Skid Steer/Track Loader)



General Appearance Inspection Points







Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	2 - Above Average Wear & Tear	
Body Panel Condition	Visible chipped paint or dents, Areas of surface rust observed	
Doors / Canopy Latches	0	
Steps / Ladders	3 - Normal Wear & Tear	
Handrails	2 - Above Average Wear & Tear	
Handrails Condition	Bent or broken railings	
Comments	Bent left hand rail	
Glass	3 - Normal Wear & Tear	
Mirrors	3 - Normal Wear & Tear	
Exterior Lights	1 - Service Required	
Exterior Lights Condition	One or more exterior lights are non-operational	
Comments	Top right light damaged	
Overall Exterior	2 - Above Average Wear & Tear	
Comments	Above average wear and tear due to bent hand rail, areas of surface rust observed at rear of machine and scratches and dents to rear of machine	

Control Station Inspection Points

Control Station

Control Station Photos

Inspection Report (Skid Steer/Track Loader)

Control Station Photos					
					
					
					
					
					
Control Station Type	Open Cab (OROPS)				
Control Type	Pilot Controls				
Control Configuration	Configurable (SAE and ISO)				
Seat	2 - Above Average Wear & Tear				
Seat Condition	Seat(s) is damaged due to sun exposure; fading, cracking observed, Seat belt secures properly				
Cabin Lights	3 - Normal Wear & Tear				
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly				
Safety Lock Out / Stop	3 - Normal Wear & Tear				
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional				
Controls & Switches	3 - Normal Wear & Tear				
Controls & Switches Condition	All switches are installed and functional				
Hour Meter Activity	3 - Normal Wear & Tear				
Hour Meter Condition	Hour meter is functional and in good condition				
Other Gauge Activity	3 - Normal Wear & Tear				
Other Gauge Condition	All cockpit gauges are functional and in good condition				
Heater & A/C	0				



Inspection Report (Skid Steer/Track Loader)

Travel Alarm	0
Horn	3 - Normal Wear & Tear
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling

Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate					
Engine Compartment Photos					
Engine Type (Make, Model, Cylinders, Hp)	Unable to verify				
Emissions Tier	Undetermined				
Engine Serial Number	Unable to verify				
Engine Fuel Type	Diesel				
Blow-by (Visual Observation Check)	No				



Inspection Report (Skid Steer/Track Loader)

Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Radiator	3 - Normal Wear & Tear
Belts	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Water Pump	3 - Normal Wear & Tear
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components, Very dirty
Overall Engine Comments	Normal wear and tear no major issues to report

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points

Drivetrain Photos	
	
Hydrostatic Transmission?	Yes

























Inspection Report (Skid Steer/Track Loader)

Speeds	Variable Speed
Drive Type	N/A (Track Undercarriage)
Transmission Components	0
Drive Motors	3 - Normal Wear & Tear
Parking Brake	0
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report

Travel System Inspection Points

Rubber Track Undercarriage

Undercarriage Photos

Undercarriage Photos					
					
					
					
					























Inspection Points

Track Width (inches)	12.5
Track Length (inches)	5' 6"
Roller Frames	3 - Normal Wear & Tear
Track Belt	3 - Normal Wear & Tear
Rubber Belt Drive Lugs	3 - Normal Wear & Tear
Track Tensioners	3 - Normal Wear & Tear
Front Idlers	3 - Normal Wear & Tear
Rear Idlers	3 - Normal Wear & Tear
Track Rollers	3 - Normal Wear & Tear

Inspection Report (Skid Steer/Track Loader)

Sprockets	3 - Normal Wear & Tear
Overall Undercarriage Rating	3 - Normal Wear & Tear
Left Track Belt - Percent Remaining Estimate	70%
Right Track Belt - Percent Remaining Estimate	70%
Overall Comments	Normal wear and tear no major issues to report

Chassis Photos

Chassis Photos					
					
					
					
					

Chassis Inspection Points









Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Lift Arms	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Quick Coupler	3 - Normal Wear & Tear
Quick Coupler to Arms Pins	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear no major issues report

Hydraulics Overall Inspection Points














Hydraulics Overall

Hydraulic System Inspection Points

Inspection Report (Skid Steer/Track Loader)

Hydraulic System Photos	    
	  
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	    
	    
	  
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear

Bucket Inspection Points

Bucket Photos	    
	
Bucket	3 - Normal Wear & Tear
Bucket Edge / Deflectors	3 - Normal Wear & Tear

Functional Test

Functionality Assessment

Functionality Assessment

Inspection Report (Skid Steer/Track Loader)

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Normal wear care no major issues to report

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	
Interior Rating	2 - Above Average Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
What's Great About the Machine	The great thing about this machine is that it starts right up with no abnormal noises heard	
What Needs Work	The things that need work on this machine are that left-hand railing, top right light and bent manual release levers for bucket.	
Date/Time	05-30-2024	
Inspector Name	Javier Bocanegra	