




Inspection Report (Skid Steer/Track Loader)

General Info

B&B Stock Number	A9490757
Year	2022
Make	Case
Model	TV450B
Serial Number	JAFTV450KMM405299
Serial Plate Photo	
Hour Meter Reading	120.5
Hour Meter Photo	
Previous Application (e.g., earth moving, mining, demolition, etc)	Earth moving

Inspection Report (Skid Steer/Track Loader)

Location / GPS	
Lat: 31.800857543945312 Long: -81.24271457846582	

Dimensions

A. Length (ft and inches)	10ft 2in without bucket/attachment
B. Width (ft and inches)	6ft 5 in excluding bucket
C. Height (ft and inches)	6 feet and 8 inches
Operational Weight (lbs)	10,610 lbs

Features and Configuration


Travel System	Track Undercarriage
Bucket	Yes
Bucket Specs	84 inch wide
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
High Flow	Yes
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	Yes
OMM (Operator & Maintenance Manual)	Yes
Telematics	Yes
Other Configuration Details / Notes	No visible damage

Exterior 360 Walkaround

Inspection Report (Skid Steer/Track Loader)

360 Walkaround & Operating Video

































Walkaround Photos & Operating Video

Exterior Walkaround Photos					
					
Operating Video	Click to Download				

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos					
					
					
					
					
					
					

Inspection Report (Skid Steer/Track Loader)


General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	5 - Like New, Recently Replaced	
Doors / Canopy Latches	5 - Like New, Recently Replaced	
Steps / Ladders	5 - Like New, Recently Replaced	
Handrails	5 - Like New, Recently Replaced	
Glass	5 - Like New, Recently Replaced	
Mirrors	5 - Like New, Recently Replaced	
Exterior Lights	5 - Like New, Recently Replaced	
Overall Exterior	5 - Like New, Recently Replaced	
Comments	No visible damage	

Control Station Inspection Points

Control Station

Control Station Photos

Control Station Photos	
Control Station Type	Enclosed Cab (EROPS)
Control Type	Pilot Controls
Control Configuration	Configurable (SAE and ISO)
Seat	5 - Like New, Recently Replaced
Cabin Lights	5 - Like New, Recently Replaced
Safety Lock Out / Stop	5 - Like New, Recently Replaced
Controls & Switches	5 - Like New, Recently Replaced
Hour Meter Activity	5 - Like New, Recently Replaced



Inspection Report (Skid Steer/Track Loader)

Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	5 - Like New, Recently Replaced
Heater & A/C	5 - Like New, Recently Replaced
Travel Alarm	5 - Like New, Recently Replaced
Horn	5 - Like New, Recently Replaced
Backup Camera	5 - Like New, Recently Replaced
Control Station Overall Rating	5 - Like New, Recently Replaced

Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate					
Engine Compartment Photos					

Inspection Report (Skid Steer/Track Loader)

Engine Type (Make, Model, Cylinders, Hp)	Fiat 3.4 liter
Emissions Tier	Tier 4F
Engine Serial Number	No tag
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	5 - Like New, Recently Replaced
Battery Condition	Clean & dry appearance, tight connections
Radiator	5 - Like New, Recently Replaced
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	5 - Like New, Recently Replaced
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	5 - Like New, Recently Replaced
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	5 - Like New, Recently Replaced
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Appearance	5 - Like New, Recently Replaced
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Appearance	5 - Like New, Recently Replaced
Oil Appearance Notes	Clean oil appearance, no signs of cross contamination
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	5 - Like New, Recently Replaced
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
Overall Engine Rating	5 - Like New, Recently Replaced
Overall Engine Appearance	Clean & dry


Inspection Report (Skid Steer/Track Loader)

Overall Engine Comments	No issues
-------------------------	-----------

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points

Drivetrain Photos	
Drive Type	N/A (Track Undercarriage)
Transmission Components	5 - Like New, Recently Replaced
Transmission Condition	Good forward and reverse function
Parking Brake	5 - Like New, Recently Replaced
Overall Drivetrain Rating	5 - Like New, Recently Replaced
Overall Drivetrain Comments	No issues


Travel System Inspection Points

Rubber Track Undercarriage

Undercarriage Photos

Undercarriage Photos	
----------------------	--

Inspection Report (Skid Steer/Track Loader)




Inspection Points

Track Width (inches)	1 foot and 6 inches
Track Length (inches)	64.5 inches on ground
Roller Frames	5 - Like New, Recently Replaced
Track Belt	5 - Like New, Recently Replaced
Rubber Belt Drive Lugs	5 - Like New, Recently Replaced
Track Tensioners	5 - Like New, Recently Replaced
Front Idlers	5 - Like New, Recently Replaced
Rear Idlers	5 - Like New, Recently Replaced
Track Rollers	5 - Like New, Recently Replaced
Overall Undercarriage Rating	5 - Like New, Recently Replaced
Left Track Belt - Percent Remaining Estimate	90%
Right Track Belt - Percent Remaining Estimate	90%
Overall Comments	No issues

Chassis Photos

Inspection Report (Skid Steer/Track Loader)



Chassis Inspection Points

Frame	5 - Like New, Recently Replaced
Stance	5 - Like New, Recently Replaced
Lift Arms	5 - Like New, Recently Replaced
Chassis to Arm Pins	5 - Like New, Recently Replaced
Quick Coupler	5 - Like New, Recently Replaced
Quick Coupler to Arms Pins	5 - Like New, Recently Replaced
Overall Chassis	5 - Like New, Recently Replaced
Overall Chassis Comments	No issues














Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points




Inspection Report (Skid Steer/Track Loader)

					
					
					
Wet or Damp Hydraulic Lines / Fittings	No				
Hydraulic Lines/Fittings	5 - Like New, Recently Replaced				
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition				
Hydraulic Pump(s)	5 - Like New, Recently Replaced				
Unusual Noises	No				
Hydraulic Pump Notes	No unusual noises heard during operation				

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos					
					
					

Inspection Report (Skid Steer/Track Loader)

		
Mounting Pins	5 - Like New, Recently Replaced	
Cylinder Oil Leaks	No	
Comments	No issues	
Hydraulic System Overall	5 - Like New, Recently Replaced	
Comments	No issues	

Bucket Inspection Points

Bucket Photos					
					
Bucket	5 - Like New, Recently Replaced				
Bucket Edge / Deflectors	5 - Like New, Recently Replaced				

Functional Test

Functionality Assessment

Functionality Assessment

Engine	5 - Like New, Recently Replaced
Transmission/Drivetrain	5 - Like New, Recently Replaced
Travel (Forward/Reverse/Steering)	5 - Like New, Recently Replaced
Brakes	5 - Like New, Recently Replaced
Hydraulic System	5 - Like New, Recently Replaced
Electric Operating System	5 - Like New, Recently Replaced
Controls	5 - Like New, Recently Replaced
Safety Systems	5 - Like New, Recently Replaced
Core Functions	5 - Like New, Recently Replaced
Attachments	5 - Like New, Recently Replaced
Overall Functional Test Comments	No issues

Inspection Report (Skid Steer/Track Loader)

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	5 - Like New, Recently Replaced	
Interior Rating	5 - Like New, Recently Replaced	
Safety Rating	5 - Like New, Recently Replaced	
Quality Rating	5 - Like New, Recently Replaced	
Functionality Rating	5 - Like New, Recently Replaced	
Overall Rating	5 - Like New, Recently Replaced	
Summary Video	Click to Download	
What's Great About the Machine	Like new condition and low hours	
What Needs Work	N/A	
Date/Time	05-23-2024	
Inspector Name	Raffaele Martino	