



## Inspection Report (On-Highway Service Truck)

### General Info

B&B Stock Number	A3608076
Year	2007
Make	International
Model	4300
Serial Number	1HTMMAAN68H417399
Serial Plate	
Odometer Reading	144099
Odometer	
Previous Application (e.g., earth moving, mining, demolition, etc)	Tree trimming

### Dimensions

Length (ft and inches)	25'
Width (ft and inches)	8'
Height (ft and inches)	12' 2"
Wheelbase (ft and inches)	15' 6"
GVWR (lbs)	33000

### Features and Configuration

## Inspection Report (On-Highway Service Truck)

Drive Type	4X2
Overdrive	No
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
Engine Brake Configuration	2 Position
Differential Lock	No
Auxiliary Engine	No
Liftgate	No
Generator	No
Welder	No
Air Compressor	No
Crane	No
Stabilizer Jacks	Yes
Telematics	No
OMM (Operator & Maintenance Manual)	No

### Exterior 360 Walkaround

#### 360 Walkaround & Operating Video

#### Walkaround Photos & Operating Video


Exterior Walkaround Photos	
Operating Video	<a href="#">Click to Download</a>
Additional Video	<a href="#">Click to Download</a>
Additional Video	<a href="#">Click to Download</a>

### General Appearance Inspection Points

#### General Appearance

## Inspection Report (On-Highway Service Truck)

### General Appearance Photos



### General Appearance Inspection Points

## Inspection Report (On-Highway Service Truck)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	
3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	
4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	

Body Panels	2 - Above Average Wear & Tear
Body Panel Condition	Large dents or cracks, Areas of surface rust observed
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	2 - Above Average Wear & Tear
Steps / Ladders Condition	Bent or broken steps or rungs
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	2 - Above Average Wear & Tear
Mirror Condition	Major chips or cracks observed
Exterior Lights	2 - Above Average Wear & Tear
Exterior Lights Condition	Major chip or cracks seen on light casings
Overall Exterior	2 - Above Average Wear & Tear
Comments	Above average wear and tear due to best steps, cracked passenger side mirror, Passenger side ember lens missing and areas of surface rust observed near rear right tire











### Cab Inspection Points

#### On Highway - Cab

#### Cab Interior Photos

Cab Interior Photos	
---------------------	--







## Inspection Report (On-Highway Service Truck)

	    
	    
Odometer Activity	3 - Normal Wear & Tear
Odometer	Odometer is working and in good condition
Controls/Switches/Gauges	3 - Normal Wear & Tear
Controls/Switches/Gauges	All switches/gauges are in good condition and functioning
Brake System Type	Air Brakes
Air Brakes Build Correct Pressure	Yes
Clutch	0
Horn	3 - Normal Wear & Tear
Reverse Alarm / Backup Camera	3 - Normal Wear & Tear
Heater & A/C	3 - Normal Wear & Tear
Interior Lights	3 - Normal Wear & Tear
Seats/Seat Belts	3 - Normal Wear & Tear
Cab Interior Overall	3 - Normal Wear & Tear
















## Engine Inspection Points

### Engine

### Engine Compartment Photos

Engine Data Plate	
Engine Compartment Photos	    

## Inspection Report (On-Highway Service Truck)

	    
	    
	    
Engine Type (Make, Model, Cylinders, Hp)	Unable to verify
Emissions Tier	Undetermined
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	Yes
Engine Smoke Notes	Other (see comments)
Comments	Smell of burning oil during operation
Engine Exhaust Color	Black
Battery	3 - Normal Wear & Tear
Radiator	2 - Above Average Wear & Tear
Radiator Condition	Other (see comments)
Comments	Oil and debris all over component
Belts	2 - Above Average Wear & Tear
Belt Condition	Other (see comments)
Comments	Belts covered in oil
Hoses	2 - Above Average Wear & Tear
Hose Condition	Other (see comments)
Water Pump	2 - Above Average Wear & Tear
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Oil Leaks	Yes
Oil Leak Notes	Active dripping and/or oil pooling observed
Oil Appearance	2 - Above Average Wear & Tear


























## Inspection Report (On-Highway Service Truck)

Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	1 - Service Required
Overall Engine Appearance	Active leaks/pooling observed in & around engine compartment
Overall Engine Comments	Major oil leak in engine compartment, oil all over hoses belts, and other major components in the engine compartment

### Chassis & Drivetrain Inspection Points

#### On-Highway: Underbody Components

#### Chassis & Drivetrain Photos

Chassis & Drivetrain Underside Photos					
					
					
					
					

### Chassis Inspection Points

Frame	2 - Above Average Wear & Tear
Comments	Areas of rust corrosion observed
Suspension	3 - Normal Wear & Tear
Steer Axle	3 - Normal Wear & Tear
Steering Components	3 - Normal Wear & Tear
Overall Chassis Condition	3 - Normal Wear & Tear

## Inspection Report (On-Highway Service Truck)

Overall Chassis Comments	Areas of rusted corrosion underneath the frame throughout the truck
--------------------------	---




### Drivetrain Inspection Points

Transmission Info (Make/Model)	Unable to verify
Transmission Type	Automatic
Transmission	3 - Normal Wear & Tear
PTO	3 - Normal Wear & Tear
Rear Differential	3 - Normal Wear & Tear
Front Differential	0
Brake Shoe Thickness	50%
Air Brake System Leaks	No
Air Brake Hose Condition	3 - Normal Wear & Tear
Overall Drivetrain Condition	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report

### Wheels & Tires Inspection Points

#### Wheels & Tires

#### Wheels & Tires Inspection Points

Wheel Type	Pneumatic
Wheel Seal Leaks	No
Tire Brand	Goodyear
Tire Size	11R22.5
Front Left Tire - Ratio Remaining	70%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	90%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	50%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	50%








































## Inspection Report (On-Highway Service Truck)

Rear Left Tire Photos	 
Wheels & Hubs	3 - Normal Wear & Tear

### Inspection Points

#### Service Truck Body

#### Inspection Points: Tool Truck Body

Tool Truck Body Photos	    
	    
	    
	    
	    
	    
	    
	 
Service Body	2 - Above Average Wear & Tear
Comments	Surface rust observed and dents observed
Toolboxes	2 - Above Average Wear & Tear
Comments	Dense and surface rust observed
Liftgate Function	0

## Inspection Report (On-Highway Service Truck)

Stabilizer Jacks	3 - Normal Wear & Tear
Stabilizer Jacks Functional	Operating as expected
Stabilizer Jacks Photos	

### Functional Test

#### Functionality Assessment

#### Functionality Assessment

Engine	2 - Above Average Wear & Tear
Comments	Smell of burning oil while in operation
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	The truck and attachment worked as designed, smell of burning oil while engine in operation

### Inspection Summary

#### Overall Assessment

Inspection Rating Criteria	<table border="1"> <thead> <tr> <th>Rating Scale</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>1 - Service Required</td> <td>Requires immediate repairs to function as expected.</td> </tr> <tr> <td>2 - Above Average Wear &amp; Tear</td> <td>Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.</td> </tr> <tr> <td>3 - Normal Wear &amp; Tear</td> <td>Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.</td> </tr> <tr> <td>4 - Very Light or Minimal Wear</td> <td>Exhibits very minimal wear. Operation is better than expected given age and usage.</td> </tr> <tr> <td>5 - Like New, Recently Replaced</td> <td>Excellent condition, free of visible wear or damage. Operation is within factory specifications.</td> </tr> </tbody> </table>	Rating Scale	Explanation	1 - Service Required	Requires immediate repairs to function as expected.	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
	Rating Scale	Explanation											
	1 - Service Required	Requires immediate repairs to function as expected.											
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.											
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.											
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.											
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.												
Exterior Rating	2 - Above Average Wear & Tear												
Interior Rating	3 - Normal Wear & Tear												
Safety Rating	3 - Normal Wear & Tear												
Quality Rating	2 - Above Average Wear & Tear												



## Inspection Report (On-Highway Service Truck)

<b>Functionality Rating</b>	3 - Normal Wear & Tear
<b>Overall Rating</b>	2 - Above Average Wear & Tear
<b>Summary Video</b>	<a href="#">Click to Download</a>
<b>What's Great About the Machine</b>	The great thing about this truck is that it starts right up with no abnormal noises heard and both the boom and bucket functions work as designed.
<b>What Needs Work</b>	The things that need work on this truck are the oil residue throughout engine compartment, The signs of rust corrosion underneath the truck and the loose entry steps to the cab
<b>Date/Time</b>	06-24-2024
<b>Inspector Name</b>	Javier Bocanegra