

Inspection Report (On-Highway Truck Cab + Chassis)

General Info

B&B Stock Number	A7538858
Year	2003
Make	International
Model	Pro star
Serial Number	3HSDJSJRXD156803
Serial Plate	
Odometer Reading	202423
Odometer	
Current Inspection / State Cert / DOT	2023
Previous Application (e.g., earth moving, mining, demolition, etc)	Inner city hauling

Dimensions

Length (ft and inches)	24'
Width (ft and inches)	8'
Height (ft and inches)	12'9"
Wheelbase (ft and inches)	15' 5"
GVWR (lbs)	52000

Inspection Report (On-Highway Truck Cab + Chassis)







Features and Configuration

Drive Type	6X4
Overdrive	No
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	No
Engine Brake	3 Position
Differential Lock	No
Auxiliary Engine	No
Liftgate	No
Telematics	No
OMM (Operator & Maintenance Manual)	No

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	
Operating Video	Click to Download
Additional Video	Click to Download
Additional Video	Click to Download


General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos	    
--------------------------	--

Inspection Report (On-Highway Truck Cab + Chassis)



General Appearance Inspection Points


Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Steps / Ladders	3 - Normal Wear & Tear	
Handrails	3 - Normal Wear & Tear	
Glass	3 - Normal Wear & Tear	
Mirrors	3 - Normal Wear & Tear	
Exterior Lights	3 - Normal Wear & Tear	
Overall Exterior	3 - Normal Wear & Tear	
Comments	Normal wear and tear no major issues to report	

Inspection Report (On-Highway Truck Cab + Chassis)

Cab Inspection Points

On Highway - Cab

Cab Interior Photos






Cab Interior Photos	
Odometer Activity	3 - Normal Wear & Tear
Controls/Switches/Gauges	3 - Normal Wear & Tear
Brake System Type	Air Brakes
Air Brakes Build Correct Pressure	Yes
Clutch	0
Horn	3 - Normal Wear & Tear
Reverse Alarm / Backup Camera	0
Heater & A/C	3 - Normal Wear & Tear
Heat & A/C	Heater and A/C work as expected
Interior Lights	4 - Very Light or Minimal Wear
Seats/Seat Belts	3 - Normal Wear & Tear
Cab Interior Overall	3 - Normal Wear & Tear

Engine Inspection Points

Engine

Engine Compartment Photos

Inspection Report (On-Highway Truck Cab + Chassis)

Engine Data Plate	
Engine Compartment Photos	
	
	
	
Engine Type (Make, Model, Cylinders, Hp)	Unable to verify
Emissions Tier	Undetermined
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Radiator	3 - Normal Wear & Tear
Belts	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Water Pump	3 - Normal Wear & Tear































Inspection Report (On-Highway Truck Cab + Chassis)

Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	2 - Above Average Wear & Tear
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Engine shows sign of above average wear and tear due to dried seepage on engine components

Chassis & Drivetrain Inspection Points

On-Highway: Underbody Components

Chassis & Drivetrain Photos

Chassis & Drivetrain Underside Photos					
					
					
					
					
					

Inspection Report (On-Highway Truck Cab + Chassis)



Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Suspension	3 - Normal Wear & Tear
Steer Axle	3 - Normal Wear & Tear
Steering Components	3 - Normal Wear & Tear
Overall Chassis Condition	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear no major issues to report


Drivetrain Inspection Points

Transmission Info (Make/Model)	Unable to verify
Transmission Type	Automatic
Transmission	3 - Normal Wear & Tear
PTO	0
Rear Differential	3 - Normal Wear & Tear
Front Differential	3 - Normal Wear & Tear
Brake Shoe Thickness	50%
Air Brake System Leaks	No
Air Brake Hose Condition	3 - Normal Wear & Tear
Overall Drivetrain Condition	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report







Wheels & Tires Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points





Wheel Type	Pneumatic
Wheel Seal Leaks	No
Tire Brand	Dplus tires
Tire Size	295/75R22.5
Front Left Tire - Ratio Remaining	70%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	70%

Inspection Report (On-Highway Truck Cab + Chassis)

Front Right Tire Photos	 
Rear Right Tire - Ratio Remaining	90%
Rear Right Tire Photos	 
Rear Left Tire - Ratio Remaining	50%
Rear Left Tire Photos	 
Wheels & Hubs	3 - Normal Wear & Tear

Additional Axle Inspection

Additional Axle Inspection Points

Axle Description & Position	Center axle
Steerable?	No
Drop Axle?	No
Super Dump?	No
Axle Condition	3 - Normal Wear & Tear
Wheels & Tires	3 - Normal Wear & Tear
Wheels & Tires Photos	   
Tire Brand	Green max
Tire Size	295/75R22.5
Left Tire(s) Ratio Remaining	50%
Right Tire(s) Ratio Remaining	90%

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear

Inspection Report (On-Highway Truck Cab + Chassis)

Hydraulic System	0
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	0
Overall Functional Test Comments	Truck functions as designed by manufacturer

Inspection Summary

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	
Interior Rating	3 - Normal Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
What's Great About the Machine	The great thing about this machine is that it starts right up with no abnormal noises heard	
What Needs Work	The thing that needs work on this truck is the dried seepage on a few of the components in the engine compartment	
Date/Time	06-25-2024	
Inspector Name	Javier Bocanegra	