



Inspection Report (Forklift)

General Info

| | |
|---------------------------|--|
| B&B Stock Number | A3029199 |
| Year | 2022 |
| Make | Doosan |
| Model | G25E-7 |
| Serial Number | Fga1m-1290-00986 |
| Serial Plate Photo |  |
| Engine Hour Meter Reading | 1531 |
| Engine Hour Meter Photo |  |
| Lifting Hour Meter | N/a |

Dimensions

| | |
|---------------------------|--------------------|
| A. Length (ft and inches) | 8'5" without forks |
| B. Width (ft and inches) | 3'10" |
| C. Height (ft and inches) | 7'2" |
| Operational Weight (lbs) | 9122 |

Features and Configuration

| | |
|-------------------------|--------------------------------|
| Max Lift Capacity | 4600 |
| Forks / Work Tool Specs | Forks - see attachment section |

Inspection Report (Forklift)

| | |
|-------------------------------------|-------|
| Side Shift | Yes |
| Tilt Carriage | No |
| Carriage Extend | No |
| Tilt Mast | Yes |
| Frame Leveling | No |
| Additional Attachment(s)? | No |
| Auxiliary Hydraulics | No |
| Tire Type | Solid |
| Heat | No |
| A/C | No |
| Radio | No |
| Backup Camera | No |
| OMM (Operator & Maintenance Manual) | No |
| Telematics | No |

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

| | |
|----------------------------|--|
| Exterior Walkaround Photos |  |
| Operating Video | Click to Download |

General Appearance Inspection Points

General Appearance

General Appearance Photos

| | |
|--------------------------|--|
| Close-up Exterior Photos |  |
|--------------------------|--|

Inspection Report (Forklift)



General Appearance Inspection Points

| Inspection Rating Criteria | Rating | Explanation |
|----------------------------------|--|---|
| | 5 | Light or minimal wear for its age |
| | 4 | Expected wear and tear for its age, operates as expected |
| | 3 | Above average wear and tear for its age, still operates as expected |
| | 2 | Heavy wear, is operable but needs attention |
| | 1 | Requires repair(s) to function as expected |
| Body Panels | 4 - Expected Wear - Fully Operable | |
| Body Panel Condition | Expected chipped paint or dents for its age. | |
| Doors / Canopy Latches | 0 | |
| Steps / Ladders | 4 - Expected Wear - Fully Operable | |
| Steps / Ladders Condition | Steps/ladders are fully intact and appear structurally sound | |
| Handrails | 4 - Expected Wear - Fully Operable | |
| Handrails Condition | Handrails are fully intact and appear structurally sound | |
| Glass | 4 - Expected Wear - Fully Operable | |
| Glass Condition | Minor chips or cracks observed, Other (see comments), Not applicable, no glass | |
| Mirrors | 4 - Expected Wear - Fully Operable | |
| Mirror Condition | Minor chips or cracks observed | |
| Exterior Lights | 4 - Expected Wear - Fully Operable | |
| Exterior Lights Condition | No visible damage, lighting system is operational | |
| Overall Exterior | 4 - Expected Wear - Fully Operable | |
| Comments | Expected scrapes and scratches for its age but in good condition | |


Control Station Inspection Points

Control Station

Control Station Photos



Inspection Report (Forklift)





| | |
|-----------------------------------|---|
| Control Station Type | Open Cab (OROPS) |
| Control Type | Other |
| Control Configuration | N/A |
| Seat | 4 - Expected Wear - Fully Operable |
| Cabin Lights | 0 |
| Safety Lock Out / Stop | 4 - Expected Wear - Fully Operable |
| Controls & Switches | 4 - Expected Wear - Fully Operable |
| Hour Meter Activity | 4 - Expected Wear - Fully Operable |
| Other Gauge Activity | 0 |
| Heater & A/C | 0 |
| Travel Alarm | 0 |
| Horn | 5 - Very Light or Minimal Wear |
| Backup Camera | 0 |
| Control Station Overall Rating | 4 - Expected Wear - Fully Operable |
| |  29.771202, -95.174291 |
| Control Station Overall Condition | Good cabin appearance, solid floors, panels, and ceiling |

Engine Inspection Points

Engine

Engine Compartment Photos

Inspection Report (Forklift)

| | | | | | |
|---|--|--|--|--|--|
| Engine Data Plate |  | | | | |
| Engine Compartment Photos |  | | | | |
| |  | | | | |
| |  | | | | |
| Engine Type (Make, Model, Cylinders, Hp) | Propane | | | | |
| Emissions Tier | Other (see comments) | | | | |
| Engine Fuel Type | LPG | | | | |
| Blow-by (Visual Observation Check) | No | | | | |
| Unusual Noises (Upon Start-up, Idle, Shutdown) | No | | | | |
| Engine Smoke (Upon Start-up, Idle, Shutdown) | No | | | | |
| Battery | 4 - Expected Wear - Fully Operable | | | | |
| Battery Condition | Clean & dry appearance, tight connections | | | | |



Inspection Report (Forklift)

| | |
|---|--|
| Radiator | 4 - Expected Wear - Fully Operable |
| Belts | 4 - Expected Wear - Fully Operable |
| Hoses | 4 - Expected Wear - Fully Operable |
| Water Pump | 4 - Expected Wear - Fully Operable |
| Cooling System Leaks | No |
| Coolant Appearance | 4 - Expected Wear - Fully Operable |
| Oil Leaks | No |
| Oil Appearance | 0 |
| Fuel Leaks | No |
| Equipped with DPF (Diesel Particulate Filter) | N/A |
| Requires DEF (Diesel Exhaust Fluid) | No |
| Overall Engine Rating | 4 - Expected Wear - Fully Operable |
| Overall Engine Appearance | Clean & dry |
| Overall Engine Comments | Engine appears to run smoothly with no audible or visual issues. |

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points





| | |
|-----------------------------|--|
| Drivetrain Photos |  |
| |  |
| Hydrostatic Transmission? | No |
| Drive Type | 2WD |
| Differential Lock | No |
| Transmission Components | 4 - Expected Wear - Fully Operable |
| Transmission Condition | Good forward and reverse function |
| Parking Brake | 4 - Expected Wear - Fully Operable |
| Overall Drivetrain Rating | 4 - Expected Wear - Fully Operable |
| Overall Drivetrain Comments | Appears to be in good working order. |

Inspection Report (Forklift)

| | |
|------------|------------------------------------|
| Front Axle | 4 - Expected Wear - Fully Operable |
| Rear Axle | 4 - Expected Wear - Fully Operable |

Wheels & Tires

Wheels & Tires Inspection Points

| | |
|------------------------------------|---|
| Wheel Type | Solid |
| Wheel Seal Leaks | No |
| Tire Brand | Nexen |
| Tire Size | See photos |
| Front Left Tire - Ratio Remaining | 70% |
| Front Left Tire Photos |  |
| Front Right Tire - Ratio Remaining | 70% |
| Front Right Tire Photos |  |
| Rear Right Tire - Ratio Remaining | 70% |
| Rear Right Tire Photos |  |
| Rear Left Tire - Ratio Remaining | 70% |
| Rear Left Tire Photos |  |
| Wheels & Hubs | 4 - Expected Wear - Fully Operable |

Chassis Inspection Points

| | | | | | |
|----------------|---|---|--|---|---|
| Chassis Photos |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  | |


Inspection Report (Forklift)

| | |
|--------------------------|--|
| Frame | 4 - Expected Wear - Fully Operable |
| Stance | 4 - Expected Wear - Fully Operable |
| Carriage Appearance | 4 - Expected Wear - Fully Operable |
| Mast Condition | 4 - Expected Wear - Fully Operable |
| Chain / Tensioners | 4 - Expected Wear - Fully Operable |
| Rollers & Guides | 4 - Expected Wear - Fully Operable |
| Overall Chassis | 4 - Expected Wear - Fully Operable |
| Overall Chassis Comments | Sturdy and runs smooth, no apparent bends or damage. |


Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

| | |
|--------------------------------------|---|
| Hydraulic System Photos |  |
| Hydraulic Lines/Fittings | 4 - Expected Wear - Fully Operable |
| Hydraulic Lines / Fittings Condition | Hydraulic lines & fittings are clean and in good condition |
| Hydraulic Pump(s) | 4 - Expected Wear - Fully Operable |
| Unusual Noises | No |
| Hydraulic Pump Notes | No unusual noises heard during operation |

Hydraulic Cylinder Inspection Points

| | |
|---------------------------|--|
| Hydraulic Cylinder Photos |  |
| Mounting Pins | 4 - Expected Wear - Fully Operable |
| Cylinder Oil Leaks | No |
| Hydraulic System Overall | 4 - Notable Wear - Fully Operable |


Inspection Report (Forklift)

| | |
|----------|-------------------|
| Comments | Operates smoothly |
|----------|-------------------|

Additional Attachments

Additional Attachment(s)

Additional Attachments

| | |
|-------------------------|--|
| Attachment Type | Fork |
| Attachment Size / Specs | L-3ft11in, W-4in |
| Attachment Photos |  |

Functional Test

Functionality Assessment

Functionality Assessment

| | |
|-----------------------------------|--|
| Engine | 4 - Expected Wear - Fully Operable |
| Transmission/Drivetrain | 4 - Expected Wear - Fully Operable |
| Travel (Forward/Reverse/Steering) | 4 - Expected Wear - Fully Operable |
| Brakes | 4 - Expected Wear - Fully Operable |
| Hydraulic System | 4 - Expected Wear - Fully Operable |
| Electric Operating System | 4 - Expected Wear - Fully Operable |
| Controls | 4 - Heavy Wear - Needs Attention |
| Safety Systems | 4 - Expected Wear - Fully Operable |
| Core Functions | 4 - Expected Wear - Fully Operable |
| Attachments | 4 - Expected Wear - Fully Operable |
| Overall Functional Test Comments | Machine operates as expected with no visual or audible issues. |

Overall Assessment

Overall Assessment

| | | |
|----------------------------|------------------------------------|---|
| Inspection Rating Criteria | Rating Scale | Explanation |
| | 1 - Service Required | Requires immediate repairs to function as expected. |
| | 2 - Above Average Wear & Tear | Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed. |
| | 3 - Normal Wear & Tear | Exhibits wear that is consistent with age and usage. Operation is normal, and as expected. |
| | 4 - Very Light or Minimal Wear | Exhibits very minimal wear. Operation is better than expected given age and usage. |
| | 5 - Like New, Recently Replaced | Excellent condition, free of visible wear or damage. Operation is within factory specifications. |
| Exterior Rating | 4 - Expected Wear - Fully Operable | |



Inspection Report (Forklift)

| | |
|---------------------------------------|---|
| Interior Rating | 4 - Expected Wear - Fully Operable |
| Safety Rating | 4 - Expected Wear - Fully Operable |
| Quality Rating | 4 - Expected Wear - Fully Operable |
| Functionality Rating | 4 - Expected Wear - Fully Operable |
| Overall Rating | 4 - Expected Wear - Fully Operable |
| What's Great About the Machine | Seat and controls are in great condition. Hydraulics appear smooth and clean. Tires still have a lot of tread left. |
| What Needs Work | Minor cosmetic damage but expected for its age/hours. |
| Date/Time | 09-10-2024 |
| Inspector Name | Ben |