Location:	Boom and	Bucket		
-	Butner,	N.C.		

Truck and Equipment Consulting, LLC - BULL DOZER INSPECTION CHECKLIST

Date (Y/M/D	9/20/2024	
Inspector Initials	H.S.	

(Basic Information)						
(Manufacturer)	Caterpillar					
(Model Number)	D1 12A					
(Serial Number)	CAT000D1CXKF00411					
(Year of Manufacturing)	2022					
(Hour Meter Reading)	171.9 Hrs					
(Engine Model) Tier 4	CAT C3.6 3.6L 80 Hp I4 TurboDiesel					
(Transmission)	Hydrostatic					
(Transmission Hydraulic Relief)	7033 psi					
(Hydraulic Relief Implement System)	2988 psi					

Specification and Dimensions					
Serial Plate/Frame Inscription		CAT000D1CXKF00411			
Cabin Canopy	(Circle)	Enclosed Cab w/A/C+Heat (working)			
EPA Certificate / Permits Posted		ROPS / FOPS level II			
Number of Shoes/Rollers		43 shoes (per side) / 6 rollers (per side)			
Track Gauge / Shoe Size		Track Gauge 59 in Width =16 in			
Fluid Capacities		Oil =2.8 gal/Coolant =4.2 gal/Hyd Tank =23.8 gal			
Fuel Tank/DEF Tank		Fuel =51.5 gal / DEF =4.9 gal			
Blade Width / Capacity		PAT Blade 104 in 1.99 yd3			
Operating Weight		17,855 lbs			
Ripper / Scarifer		N/A			
Other		Rev Camera, Slope Indicator, Travel Speed Limiter			

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

	(Check List)	Α	В	С	D	Е	(Remarks)
GENERAL	(General Appearance-Front)		Χ				Good appearance of front end components, blade No damage
APPEARANCE	(General Appearance-Rear)		Χ				Good appearance of back panels+components, grille No damage
	(General Appearance-Right)		Χ				Good appearance of panel gaps, track frame, No damage
	(General Appearance-Left)		Χ				Good appearance of left side panel gaps and panels No damage
	(General Appearance-Upper)		Χ				Good appearance of cabin, upper panel surfaces, GPS stacks No damage
	(Major / Minor Surface Rust)		Χ				No rust issues No rust seen
	(Body Panel Rust Damage / Cancer)		Χ				No panel damage No cancer
	(Visible Weld Repairs / Stress Cracks)		Χ				No weld repairs No stress cracks seen
	(Glass Condition)		Χ				Good glass appearance No damage
	(Chassis / Undercarriage Damage)		Χ				Very Muddy Site No damage Good underside panel gaps
	(Operator Cabin)		Χ				Solid Floors, Good appearance of panels + gaps Dirty and muddy
OPERATOR'S	(Operator Controls and Switches)		Χ				Complete Switchgear Good appearance and Functionality No damage
COCKPIT	(Hour Meter Activity)		Χ				Hours Meter Working
	(Other Gauge Activity)		Χ				Display Clear and Sharp No Error Codes Reverse Camera Working
	(Door / Canopy Latches)		Χ				Doors, Engine cover + locks Good Working Condition
	(Safety - Horn / First Aid Kit)		Χ				Rev Alarm Working / Yes
	(Operator Seat Condition)		Χ				Seat Good Condition
	(Safety - Seat Belts / Fire Extinguisher)		Χ				Yes
ENGINE	(Oil Color / Fluid Appearance / Particulates or Granuales)		Χ				Normal appearance No signs or smells of contamination
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		Χ				Easy start Smooth Idle No unusual engine noises at start up or shut down
	(Engine Exhaust Color - White / Blue / Black / Clear)		Χ				Clear at start up Stays Clear at Operating temp
	(Oil Leaks)		Χ				Engine compartment dry No active leaks seen
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		Χ				No smoke issues No blow by
	(Coolant Color / Fluid Appearance)		Χ				Coolant Normal appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		Χ				No leaks or damp hoses
	(Coolant Leaks from Radiator)		Χ				Radiator clean and Dry
	(Overall Engine Appearance Clean / Wet / Dry)		Χ				Engine Clean and Dry
	(Overall appearance of Hydraulic lines/fittings - worn/cracked)		Χ				Good appearance of hydraulic lines+fittings No dried seepage
HYDRAULICS	(Hydraulic Pump Sounds / Noises)		Χ				No unusual hydraulic noises during operations
OVERALL	Wet or Damp hydraulic lines and fittings / fluid leaks)		Χ				Dry
	(External Controls / Levers Condition)		Χ				Good function and condition
	(Hydraulics Service Records / Maintenance History)		Х				Filter Labeled 2/2022 @ 3 Hrs

·	· ·	·	·	CHID	DING DIN	ENICION	NS: (reff only) *A:Rema	ining Ratio 90% or more		
	(Other Remarks)			Χ		G	Good Appearance			
	(Ripper Overall Condition)						N/A			
RIPPER	(Blade Overall Condition)			Χ		Blade overall Good Appearance some minor surface cosmetics				
BLADE/	(Blade Edge)			Х	T İ	G	Good Blade Edge			
	Other Comments			Х		Good PAT n	nulti directional postioning			
		Reverse	Lift/Tilt/Angle		Х		Good Lift/Tilt/Angle	1		
	OPERATION	D	Steering/Brakes/Clutch		Х		Good Reverse Function	use (A)90% to (E) 20%		
	ODEDATION		Lift/Tilt/Angle		Х	1 1	Good Lift/Tilt/Angle	(A)00% to (E) 00%		
			Steering/Brakes/Clutch		X	1 1	Good Forward Function			
				X	1 1					
					X	1 1		Caked in mud Good appearance above average smooth surfaces + ed Caked in mud Good appearance above average smooth surfaces + ed		
HASSIS					X	1 1	Caked in mud Good appearance above average smooth surfaces + edg Caked in mud Good appearance above average smooth surfaces + edg			
	9			• •	1 1	Caked in mud Good appearance above average smooth surfaces + edge				
	U 11				1 1	Caked in mud Good overall appearance above average smooth surfaces + edge				
	· · · · · · · · · · · · · · · · · · ·				Х	1 1	Caked in mud Good overall a	Caked in mud Good overall appearance above average smooth surfaces		
				^	1 1	233 1111101 410	N/A			
-	(Angle)				X	+ +				
					,,	+				
	(Tilt)		•			+ +				
						+				
	(Lift)	(+		1, ,		
	Other Rema	,	vlindor)			+ +				
ELECTRICAL (B) (C) (C) (C) (C) (C) (C) (C) (C) (C) (C			edoll)		^ v	+ +				
					۸ ۷	++				
A NICMICCIO	, - , - , - , - , - , - , - , - , - , -	- ,	\			+				
						+	L			
						+ +				
ECTRICAL (I)			forking Condition)			+ +				
Parking Brake										
	•	ric Device Condit	ion)			+				
ELECTRICAL () () () () () () () () () () () () ()					• •	1		• • • • • • • • • • • • • • • • • • • •		
					X	1 1	B	· · · · · · · · · · · · · · · · · · ·		
					Х					

OVERALL EXTERIOR RATING: <u>B</u>	QUALITY: <u>B</u>	Length: 168 in	*B:Remaining Ratio	70% or more
OVERALL INTERIOR RATING:B	SAFETY: <u>B</u>	Width: 74.8 in (no blade)	*C:Remaining Ratio	50% or more
OVERALL PERFORMANCE: B	FUNCTIONALITY: <u>B</u>	Height: 108.9 in	*D:Remaining Ratio	20% or more
OVERALL EVALUTAION GRADE: B		Weight: 17,855 lbs	*E:Remaining Ratio	20% or less