



Inspection Report (Forklift)

General Info

B&B Stock Number	A1507305
Year	2022
Make	Doosan
Model	G25e-7
Serial Number	Fga1m-1290-02529
Serial Plate Photo	
Engine Hour Meter Reading	364
Engine Hour Meter Photo	
Lifting Hour Meter	Na

Dimensions

A. Length (ft and inches)	8ft 10in without forks
B. Width (ft and inches)	3ft 10in
C. Height (ft and inches)	7ft 2 in
Operational Weight (lbs)	9122

Features and Configuration

Max Lift Height	Unavailable
Max Lift Capacity	4600












Inspection Report (Forklift)

Forks / Work Tool Specs	Forks
Side Shift	Yes
Tilt Carriage	No
Carriage Extend	No
Tilt Mast	Yes
Frame Leveling	No
Additional Attachment(s)?	No
Auxiliary Hydraulics	No
Tire Type	Solid
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video


Exterior Walkaround Photos	    
	    
	
Operating Video	Click to Download
Additional Video	Click to Download

General Appearance Inspection Points

General Appearance

General Appearance Photos

Inspection Report (Forklift)



General Appearance Inspection Points

Inspection Rating Criteria	Rating	Explanation
	5	Light or minimal wear for its age
	4	Expected wear and tear for its age, operates as expected
	3	Above average wear and tear for its age, still operates as expected
	2	Heavy wear, is operable but needs attention
	1	Requires repair(s) to function as expected
Body Panels	4 - Expected Wear - Fully Operable	
Body Panel Condition	Good paint condition and panel fitment	
Doors / Canopy Latches	4 - Expected Wear - Fully Operable	
Steps / Ladders	4 - Expected Wear - Fully Operable	
Handrails	4 - Expected Wear - Fully Operable	
Glass	4 - Expected Wear - Fully Operable	
Mirrors	4 - Expected Wear - Fully Operable	
Exterior Lights	4 - Expected Wear - Fully Operable	
Overall Exterior	4 - Expected Wear - Fully Operable	
Comments	Lightly used and exterior is in great shape. Expected scrapes from usage but nothing notable.	




Control Station Inspection Points

Control Station

Control Station Photos



Inspection Report (Forklift)











	 	
Control Station Type	Open Cab (OROPS)	
Control Type	Other	
Control Configuration	N/A	
Seat	4 - Expected Wear - Fully Operable	
Cabin Lights	0	
Safety Lock Out / Stop	0	
Controls & Switches	4 - Expected Wear - Fully Operable	
Hour Meter Activity	4 - Expected Wear - Fully Operable	
Hour Meter Condition	Hour meter is functional and in good condition	
Other Gauge Activity	4 - Expected Wear - Fully Operable	
Heater & A/C	0	
Travel Alarm	0	
Horn	5 - Very Light or Minimal Wear	
Backup Camera	0	
Control Station Overall Rating	4 - Expected Wear - Fully Operable	
	 29.771200, -95.174150	
Control Station Overall Condition	Good cabin appearance, solid floors, panels, and ceiling	

Engine Inspection Points

Engine

Engine Compartment Photos

Inspection Report (Forklift)

Engine Data Plate					
Engine Compartment Photos	    				
	    				
Engine Type (Make, Model, Cylinders, Hp)	Doosan HMC 2.4L				
Emissions Tier	Other (see comments)				
Comments	See plate - propane				
Engine Serial Number	L4kbnd053658				
Engine Fuel Type	LPG				
Blow-by (Visual Observation Check)	No				
Unusual Noises (Upon Start-up, Idle, Shutdown)	No				
Engine Smoke (Upon Start-up, Idle, Shutdown)	No				
Engine Exhaust Color	Clear				
Battery	4 - Expected Wear - Fully Operable				
Battery Condition	Clean & dry appearance, tight connections				


Inspection Report (Forklift)

Radiator	4 - Expected Wear - Fully Operable
Belts	4 - Expected Wear - Fully Operable
Hoses	4 - Expected Wear - Fully Operable
Water Pump	4 - Expected Wear - Fully Operable
Cooling System Leaks	No
Coolant Appearance	4 - Expected Wear - Fully Operable
Oil Leaks	No
Oil Appearance	4 - Expected Wear - Fully Operable
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	N/A
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	4 - Expected Wear - Fully Operable
Overall Engine Appearance	Clean & dry, Dusty & dry
Overall Engine Comments	Engine fires right up with no unexpected noises. Low hours and appears in well kept condition.

Drivetrain Inspection Points

Drivetrain





Drivetrain Inspection Points

Drivetrain Photos					
Hydrostatic Transmission?	N/A				
Drive Type	2WD				
Differential Lock	No				
Transmission Components	4 - Expected Wear - Fully Operable				
Parking Brake	4 - Expected Wear - Fully Operable				
Overall Drivetrain Rating	4 - Expected Wear - Fully Operable				
Overall Drivetrain Comments	Appears to be in good working order.				
Front Axle	4 - Expected Wear - Fully Operable				
Rear Axle	4 - Expected Wear - Fully Operable				

Wheels & Tires

Inspection Report (Forklift)



Wheels & Tires Inspection Points

Wheel Type	Solid		
Wheel Seal Leaks	No		
Tire Brand	Chao Yang		
Tire Size	See photos		
Front Left Tire - Ratio Remaining	90%		
Front Left Tire Photos			
Front Right Tire - Ratio Remaining	90%		
Front Right Tire Photos			
Rear Right Tire - Ratio Remaining	90%		
Rear Right Tire Photos			
Rear Left Tire - Ratio Remaining	90%		
Rear Left Tire Photos			
Wheels & Hubs	4 - Expected Wear - Fully Operable		

Chassis Inspection Points

Chassis Photos					
					
					
					









Inspection Report (Forklift)

	 	
Frame	4 - Expected Wear - Fully Operable	
Stance	4 - Expected Wear - Fully Operable	
Carriage Appearance	4 - Expected Wear - Fully Operable	
Mast Condition	4 - Expected Wear - Fully Operable	
Chain / Tensioners	4 - Expected Wear - Fully Operable	
Rollers & Guides	4 - Expected Wear - Fully Operable	
Overall Chassis	4 - Expected Wear - Fully Operable	
Overall Chassis Comments	Appears to be in great shape with no misalignment or damage.	












Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos	    	
	  	
Wet or Damp Hydraulic Lines / Fittings	No	
Hydraulic Lines/Fittings	4 - Expected Wear - Fully Operable	
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition	
Hydraulic Pump(s)	4 - Expected Wear - Fully Operable	
Hydraulic Pump Notes	No unusual noises heard during operation	

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	    	
	    	
	 	


Inspection Report (Forklift)

Mounting Pins	4 - Expected Wear - Fully Operable
Cylinder Oil Leaks	No
Hydraulic System Overall	4 - Notable Wear - Fully Operable
Comments	Hydraulics run smoothly with no unusual noises

Additional Attachments

Additional Attachment(s)

Additional Attachments

Attachment Type	Forks
Attachment Size / Specs	4in x 4ft
Attachment Condition	4 - Expected Wear - Fully Operable
Attachment Photos	

Functional Test

Functionality Assessment

Functionality Assessment

Engine	4 - Expected Wear - Fully Operable
Transmission/Drivetrain	4 - Expected Wear - Fully Operable
Travel (Forward/Reverse/Steering)	4 - Expected Wear - Fully Operable
Brakes	4 - Expected Wear - Fully Operable
Hydraulic System	4 - Expected Wear - Fully Operable
Electric Operating System	4 - Expected Wear - Fully Operable
Controls	4 - Heavy Wear - Needs Attention
Safety Systems	4 - Expected Wear - Fully Operable
Core Functions	4 - Expected Wear - Fully Operable
Attachments	4 - Expected Wear - Fully Operable
Overall Functional Test Comments	Low hours and functions as expected. Engine and hydraulics operate smoothly with no unusual noises.

Overall Assessment

Overall Assessment

Inspection Report (Forklift)

Inspection Rating Criteria	Rating	Explanation
	5	Light or minimal wear for its age
	4	Expected wear and tear for its age, operates as expected
	3	Above average wear and tear for its age, still operates as expected
	2	Heavy wear, is operable but needs attention
	1	Requires repair(s) to function as expected
Exterior Rating	4 - Expected Wear - Fully Operable	
Interior Rating	5 - Very Light or Minimal Wear	
Safety Rating	4 - Expected Wear - Fully Operable	
Quality Rating	4 - Expected Wear - Fully Operable	
Functionality Rating	4 - Expected Wear - Fully Operable	
Overall Rating	4 - Expected Wear - Fully Operable	
Summary Video	Click to Download	
What's Great About the Machine	Low hours and operates like it. Appears to be well maintained and taken care of.	
What Needs Work	Nothing notable.	
Date/Time	10-15-2024	
Inspector Name	Ben	