



Inspection Report (Skid Steer/Track Loader)

General Info

B&B Stock Number	A5105639
Year	2015
Make	Caterpillar
Model	279D
Serial Number	CAT0279DVGTL01518
Serial Plate Photo	
Hour Meter Reading	5866.1
Hour Meter Photo	
Previous Application (e.g., earth moving, mining, demolition, etc)	Earth moving

Features and Configuration

Travel System	Track Undercarriage
Bucket	Yes
Bucket Specs	80"
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
High Flow	Yes
Heat	Yes

















Inspection Report (Skid Steer/Track Loader)

A/C	Yes
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

360 Walkaround & Operating Video
















Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	    
	    
	
Operating Video	Click to Download

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos	    
	    
	    

Inspection Report (Skid Steer/Track Loader)



General Appearance Inspection Points

Inspection Rating Criteria	Rating	Explanation
	5	Light or minimal wear for its age
	4	Expected wear and tear for its age, operates as expected
	3	Above average wear and tear for its age, still operates as expected
	2	Heavy wear, is operable but needs attention
	1	Requires repair(s) to function as expected
Body Panels	4 - Expected Wear - Fully Operable	
Body Panel Condition	Expected chipped paint or dents for its age.	
Doors / Canopy Latches	4 - Expected Wear - Fully Operable	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	4 - Expected Wear - Fully Operable	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	4 - Expected Wear - Fully Operable	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	2 - Heavy Wear - Needs Attention	
Glass Condition	Other (see comments)	
Comments	Roof glass missing	
Mirrors	4 - Expected Wear - Fully Operable	
Mirror Condition	Mirrors present and intact, no visible damage	
Exterior Lights	4 - Expected Wear - Fully Operable	
Exterior Lights Condition	No visible damage, lighting system is operational	
Overall Exterior	4 - Expected Wear - Fully Operable	
Comments	Expected wear and tear due to age of machine, rooftop glass missing	













Control Station Inspection Points

Control Station

Control Station Photos



Inspection Report (Skid Steer/Track Loader)
















	    
	    
	
Control Station Type	Enclosed Cab (EROPS)
Control Type	Pilot Controls
Control Configuration	Unable to confirm
Seat	4 - Expected Wear - Fully Operable
Seat Condition	Seat in good condition, no stains or tears in upholstery
Cabin Lights	4 - Expected Wear - Fully Operable
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
Safety Lock Out / Stop	4 - Expected Wear - Fully Operable
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	4 - Expected Wear - Fully Operable
Controls & Switches Condition	Switches have good functionality, expected cosmetic damage for a machine this age
Hour Meter Activity	4 - Expected Wear - Fully Operable
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	4 - Expected Wear - Fully Operable
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	4 - Expected Wear - Fully Operable
Heater & A/C Condition	Heater and A/C work as expected
Travel Alarm	4 - Expected Wear - Fully Operable
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	4 - Expected Wear - Fully Operable
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Control Station Overall Rating	4 - Expected Wear - Fully Operable
	 41.508505, -112.039922
Control Station Overall Condition	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling

Inspection Report (Skid Steer/Track Loader)

Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate					
Engine Compartment Photos					
					
					
Engine Type (Make, Model, Cylinders, Hp)	Caterpillar, c3.3B				
Emissions Tier	Undetermined				
Engine Serial Number	8EJ2504				
Engine Fuel Type	Diesel				

Inspection Report (Skid Steer/Track Loader)









Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	4 - Expected Wear - Fully Operable
Battery Condition	Dusty & dirty appearance
Radiator	4 - Expected Wear - Fully Operable
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	4 - Expected Wear - Fully Operable
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	4 - Expected Wear - Fully Operable
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	4 - Expected Wear - Fully Operable
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Appearance	4 - Expected Wear - Fully Operable
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Appearance	4 - Expected Wear - Fully Operable
Oil Appearance Notes	Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	4 - Expected Wear - Fully Operable
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Notable Wear - Fully Operable
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Dried seepage found throughout and compartment, dusty, dirty engine compartment

Drivetrain Inspection Points

Drivetrain

Inspection Report (Skid Steer/Track Loader)


























Drivetrain Inspection Points

Drivetrain Photos					
					
Hydrostatic Transmission?	Yes				
Speeds	2 Speed				
Drive Type	N/A (Track Undercarriage)				
Transmission Components	0				
Drive Motors	4 - Expected Wear - Fully Operable				
Parking Brake	4 - Expected Wear - Fully Operable				
Overall Drivetrain Rating	4 - Expected Wear - Fully Operable				
Overall Drivetrain Comments	Expected wear and tear due to age of machine no major issues to report				

Travel System Inspection Points

Rubber Track Undercarriage

Undercarriage Photos

Undercarriage Photos					
					
					
					
					

Inspection Report (Skid Steer/Track Loader)



Inspection Points

Track Width (inches)	18"
Track Length (inches)	70"
Roller Frames	4 - Expected Wear - Fully Operable
Track Belt	3 - Notable Wear - Fully Operable
Rubber Belt Drive Lugs	3 - Notable Wear - Fully Operable
Track Tensioners	4 - Expected Wear - Fully Operable
Front Idlers	4 - Expected Wear - Fully Operable
Rear Idlers	4 - Expected Wear - Fully Operable
Track Rollers	4 - Expected Wear - Fully Operable
Sprockets	4 - Expected Wear - Fully Operable
Overall Undercarriage Rating	3 - Notable Wear - Fully Operable
Left Track Belt - Percent Remaining Estimate	30%
Right Track Belt - Percent Remaining Estimate	30%
Overall Comments	Fluid leaking from behind right side sprocket

Chassis Photos



Chassis Inspection Points

Frame	4 - Expected Wear - Fully Operable
Stance	4 - Expected Wear - Fully Operable
Lift Arms	4 - Expected Wear - Fully Operable









Inspection Report (Skid Steer/Track Loader)

Chassis to Arm Pins	4 - Expected Wear - Fully Operable
Quick Coupler	4 - Expected Wear - Fully Operable
Quick Coupler to Arms Pins	4 - Expected Wear - Fully Operable
Overall Chassis	4 - Expected Wear - Fully Operable
Overall Chassis Comments	Expected wear and tear due to age of machine no major issues to report









Hydraulics Overall Inspection Points

Hydraulics Overall





Hydraulic System Inspection Points

Hydraulic System Photos					
					
Wet or Damp Hydraulic Lines / Fittings	No				
Hydraulic Lines/Fittings	4 - Expected Wear - Fully Operable				
Hydraulic Pump(s)	4 - Expected Wear - Fully Operable				
Unusual Noises	No				
Hydraulic Pump Notes	No unusual noises heard during operation				


Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos					
					
Mounting Pins	4 - Expected Wear - Fully Operable				
Cylinder Oil Leaks	No				
Hydraulic System Overall	4 - Notable Wear - Fully Operable				

Bucket Inspection Points

Bucket Photos	    				
---------------	--	--	--	--	--

Inspection Report (Skid Steer/Track Loader)

		
Bucket	3 - Notable Wear - Fully Operable	
Bucket Edge / Deflectors	3 - Notable Wear - Fully Operable	

Functional Test

Functionality Assessment

Functionality Assessment

Engine	4 - Expected Wear - Fully Operable
Transmission/Drivetrain	4 - Expected Wear - Fully Operable
Travel (Forward/Reverse/Steering)	4 - Expected Wear - Fully Operable
Brakes	4 - Expected Wear - Fully Operable
Hydraulic System	4 - Expected Wear - Fully Operable
Electric Operating System	4 - Expected Wear - Fully Operable
Controls	4 - Heavy Wear - Needs Attention
Safety Systems	4 - Expected Wear - Fully Operable
Core Functions	4 - Expected Wear - Fully Operable
Attachments	3 - Notable Wear - Fully Operable
Overall Functional Test Comments	Expected wear and tear due to age of machine no major issues to report

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating	Explanation
	5	Light or minimal wear for its age
	4	Expected wear and tear for its age, operates as expected
	3	Above average wear and tear for its age, still operates as expected
	2	Heavy wear, is operable but needs attention
	1	Requires repair(s) to function as expected
Exterior Rating	3 - Notable Wear - Fully Operable	
Interior Rating	3 - Notable Wear - Fully Operable	
Safety Rating	4 - Expected Wear - Fully Operable	
Quality Rating	4 - Expected Wear - Fully Operable	
Functionality Rating	4 - Expected Wear - Fully Operable	
Overall Rating	4 - Expected Wear - Fully Operable	

Inspection Report (Skid Steer/Track Loader)

What's Great About the Machine	The great thing about this machine is that it starts right up with no abnormal noises heard as well as during the function test there were no abnormal noises heard
What Needs Work	The things that need work on this machine are the warrant rubber tracks, oil leaking behind right side sprocket, missing roof glass, found throughout engine department
Date/Time	10-24-2024
Inspector Name	Javier Bocanegra