


## **Inspection Report (Trailer)**

#### **General Info**

	Sonoral IIIIO	
B&B Stock Number	A0748001	
Year	2020	
Make	PJ Trailers	
Model	Retractable tarp system	
Serial Number	4P5LD402XM1351479	
Serial Plate Photo	NON-Swiveling Flange Nut  275-325 Ft. Lbs.  5 8 DLT  6 8 DLT  8 BOLT  8 BOLT	
Previous Application (e.g., earth moving, mining, demolition, etc)	Hauling	

#### **Dimensions**



### **Features and Configuration**



## **Inspection Report (Trailer)**

PTO Driven	No
Air Ride	No
Equipment Ramps	Yes
Tilt Deck	No
Dump Trailer	No
Deck Extension	No
Tarp System	Yes
Spare Tire	Yes
Winch	No
OMM (Operator & Maintenance Manual)	No

## **Exterior 360 Walkaround**

## 360 Walkaround & Operating Video

## Walkaround Photos & Operating Video

Transaction in the total of a personal grade	
Exterior Walkaround Photos	18
	18
Operating Video	Click to Download
Additional Video	Click to Download

# **Trailer Inspection Points**

## **Trailer Inspection Points**

# **General Appearance Photos**





# **Inspection Report (Trailer)**



# Frame & Body

Frame & Deck Condition	4 - Expected Wear - Fully Operable
Trailer Lights/Wiring (Stop, Tail, Turn)	4 - Expected Wear - Fully Operable
Frame & Body Overall Rating	4 - Expected Wear - Fully Operable

#### Hitch

Hitch Type	Gooseneck
Strand Wear?	No
Drawbar appears structurally sound	Yes
Overall Hitch Condition	4 - Expected Wear - Fully Operable

# **Brake Components**

Brake Type	Electric Brakes
Brake Controller	Yes
Wire Connections	4 - Expected Wear - Fully Operable
Brake Shoe Thickness	70%
Emergency Brake/Break-Away Appearance	4 - Expected Wear - Fully Operable
Brake Overall Rating	4 - Expected Wear - Fully Operable

# Suspension

Suspension Overall Rating 4 - Expected Wear - Fully Operable
--

#### Wheels & Tires

Tire Brand	Good year
Tire Size	ST 235/80R16
Loose Lugs	No
Left Tires - Ratio Remaining	70%
Left Tire Photos	
Right Tires - Ratio Remaining	70%



# Inspection Report (Trailer)

Right Tire Photos	
Wheels & Hub Condition	4 - Expected Wear - Fully Operable

# **Hydraulics**

Hydraulics Overall Rating	N/A
---------------------------	-----

### **Additional Axles**

## **Additional Axle Inspection Points**

Additional Axie inspection	11 Ollito
Axle Description & Position	Tandem
Steerable?	No
Drop Axle?	No
Super Dump?	No
Weight Rating	10000
Axle Condition	4 - Expected Wear - Fully Operable
Wheels & Tires	4 - Expected Wear - Fully Operable
Wheels & Tires Photos	
Tire Brand	Good year
Tire Size	ST235/80R16
Left Tire(s) Ratio Remaining	70%
Right Tire(s) Ratio Remaining	70%

### **Functional Test**

Brakes	4 - Expected Wear - Fully Operable
Light System	4 - Expected Wear - Fully Operable
Hydraulic Controls	N/A
Winch	N/A

# **Inspection Summary**

### **Overall Assessment**



# **Inspection Report (Trailer)**

Inspection Rating Criteria	Rating	Explanation	
	5	Light or minimal wear for its age	
	4	Expected wear and tear for its age, operates as expected	
	3	Above average wear and tear for its age, still operates as expected	
	2	Heavy wear, is operable but needs attention	
	1	Requires repair(s) to function as expected	
Exterior Rating	4 - Expected Wear - Fully Operable		
Interior Rating	4 - Expected Wear - Fully Operable		
Safety Rating	4 - Expected Wear - Fully Operable		
Quality Rating	4 - Expected Wear - Fully Operable		
Functionality Rating	4 - Expected Wear - Fully Operable		
Overall Rating	4 - Expected Wear - Fully Operable		
What's Great About the Machine	The great thing about the trailer is that it is able to perform all major functions and easily to disassemble and reassemble		
What Needs Work	NA		
Date/Time	12-20-2024		
Inspector Name	Javier Bocanegra		