



## Inspection Report (Trailer)

### General Info

B&B Stock Number	A2512746
Year	2019
Make	PJ Trailers
Model	Retractable tarp system
Serial Number	4P5FD3620K1305588
Serial Plate Photo	
Previous Application (e.g., earth moving, mining, demolition, etc)	Hauling

### Dimensions

Data Plate Photo	
Length (ft and inches)	45'
Width (ft and inches)	9'
Max Height (ft and inches)	13'
Dock Height (ft and inches)	3'3"
GVWR (lbs)	25000
GAWR (lbs)	10000

### Features and Configuration








## Inspection Report (Trailer)

PTO Driven	No
Air Ride	No
Equipment Ramps	Yes
Tilt Deck	No
Dump Trailer	No
Deck Extension	No
Tarp System	Yes
Spare Tire	No
Winch	No
OMM (Operator & Maintenance Manual)	No

## Exterior 360 Walkaround

### 360 Walkaround & Operating Video
















### Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	 
Operating Video	<a href="#">Click to Download</a>
Additional Video	<a href="#">Click to Download</a>

## Trailer Inspection Points

### Trailer Inspection Points

### General Appearance Photos

Overall Trailer & Underside Photos	    
	    
	    

## Inspection Report (Trailer)



### Frame & Body

Frame & Deck Condition	4 - Expected Wear - Fully Operable
Trailer Lights/Wiring (Stop, Tail, Turn)	4 - Expected Wear - Fully Operable
Frame & Body Overall Rating	4 - Expected Wear - Fully Operable

### Hitch

Hitch Type	Gooseneck
Strand Wear?	No
Drawbar appears structurally sound	Yes
Overall Hitch Condition	4 - Expected Wear - Fully Operable

### Brake Components

Brake Type	Electric Brakes
Brake Controller	Yes
Wire Connections	4 - Expected Wear - Fully Operable
Brake Shoe Thickness	70%
Emergency Brake/Break-Away Appearance	4 - Expected Wear - Fully Operable
Brake Overall Rating	4 - Expected Wear - Fully Operable

### Suspension

Suspension Overall Rating	4 - Expected Wear - Fully Operable
---------------------------	------------------------------------

### Wheels & Tires

Tire Brand	Good ride
Tire Size	ST235/80R16
Loose Lugs	No
Left Tires - Ratio Remaining	70%

## Inspection Report (Trailer)







Left Tire Photos	  
Right Tires - Ratio Remaining	70%
Right Tire Photos	  
Wheels & Hub Condition	4 - Expected Wear - Fully Operable

## Hydraulics

Hydraulics Overall Rating	N/A
---------------------------	-----

## Additional Axles

### Additional Axle Inspection Points

Axle Description & Position	Tandem
Steerable?	No
Drop Axle?	No
Super Dump?	No
Weight Rating	10000
Axle Condition	4 - Expected Wear - Fully Operable
Wheels & Tires	4 - Expected Wear - Fully Operable
Wheels & Tires Photos	    
	
Tire Brand	Good ride
Tire Size	ST235/80R16
Left Tire(s) Ratio Remaining	70%
Right Tire(s) Ratio Remaining	70%

## Functional Test

Brakes	4 - Expected Wear - Fully Operable
Light System	4 - Expected Wear - Fully Operable
Hydraulic Controls	N/A
Winch	N/A



## Inspection Report (Trailer)

### Inspection Summary

#### Overall Assessment

Inspection Rating Criteria	Rating	Explanation
	5	Light or minimal wear for its age
	4	Expected wear and tear for its age, operates as expected
	3	Above average wear and tear for its age, still operates as expected
	2	Heavy wear, is operable but needs attention
	1	Requires repair(s) to function as expected
Exterior Rating	4 - Expected Wear - Fully Operable	
Interior Rating	4 - Expected Wear - Fully Operable	
Safety Rating	4 - Expected Wear - Fully Operable	
Quality Rating	4 - Expected Wear - Fully Operable	
Functionality Rating	4 - Expected Wear - Fully Operable	
Overall Rating	4 - Expected Wear - Fully Operable	
What's Great About the Machine	The great thing about this trailer is that it is able to perform all his major functions and it is easy to assemble and disassemble	
What Needs Work	The thing that needs work on this trailer is the rust found throughout the chassis	
Date/Time	12-20-2024	
Inspector Name	Javier Bocanegra	