



Inspection Report (Trailer)

General Info

B&B Stock Number	A7248348
Year	2021
Make	PJ Trailers
Model	Soft side tarp trailer
Serial Number	4P5LD4029M1352073
Serial Plate Photo	
Previous Application (e.g., earth moving, mining, demolition, etc)	Hauling

Dimensions

Data Plate Photo	
Length (ft and inches)	36'
Width (ft and inches)	108"
Max Height (ft and inches)	13'
Dock Height (ft and inches)	2'9"
GVWR (lbs)	25,000
GAWR (lbs)	10000

Features and Configuration











Inspection Report (Trailer)

PTO Driven	No
Air Ride	No
Equipment Ramps	Yes
Tilt Deck	No
Dump Trailer	No
Deck Extension	No
Tarp System	Yes
Spare Tire	No
Winch	No
OMM (Operator & Maintenance Manual)	No

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	    
Operating Video	Click to Download
Additional Video	Click to Download

Trailer Inspection Points

Trailer Inspection Points

General Appearance Photos

Overall Trailer & Underside Photos	    
	    
	    

Inspection Report (Trailer)



Frame & Body

Frame & Deck Condition	4 - Expected Wear - Fully Operable
Trailer Lights/Wiring (Stop, Tail, Turn)	4 - Expected Wear - Fully Operable
Frame & Body Overall Rating	4 - Expected Wear - Fully Operable

Hitch

Hitch Type	Gooseneck
Strand Wear?	No
Drawbar appears structurally sound	Yes
Overall Hitch Condition	4 - Expected Wear - Fully Operable


Brake Components

Brake Type	Electric Brakes
Brake Controller	Yes
Wire Connections	4 - Expected Wear - Fully Operable
Brake Shoe Thickness	70%
Emergency Brake/Break-Away Appearance	4 - Expected Wear - Fully Operable

Suspension

Suspension Overall Rating	4 - Expected Wear - Fully Operable
---------------------------	------------------------------------

Wheels & Tires

Tire Brand	Goodyear
Tire Size	St235/80R16
Loose Lugs	No
Left Tires - Ratio Remaining	70%
Left Tire Photos	

Inspection Report (Trailer)








		
Right Tires - Ratio Remaining	70%	
Right Tire Photos	    	
		
Wheels & Hub Condition	4 - Expected Wear - Fully Operable	

Hydraulics

Hydraulics Overall Rating	N/A
---------------------------	-----

Additional Axles

Additional Axle Inspection Points

Steerable?	No				
Drop Axle?	No				
Super Dump?	No				
Weight Rating	1000				
Axle Condition	4 - Expected Wear - Fully Operable				
Axle Condition Photos					
Wheels & Tires	4 - Expected Wear - Fully Operable				
Wheels & Tires Photos					
Left Tire(s) Ratio Remaining	70%				
Right Tire(s) Ratio Remaining	70%				

Functional Test

Brakes	4 - Expected Wear - Fully Operable
Light System	4 - Expected Wear - Fully Operable
Hydraulic Controls	N/A
Winch	N/A

Inspection Summary

Inspection Report (Trailer)

Overall Assessment

Inspection Rating Criteria	Rating	Explanation
	5	Light or minimal wear for its age
	4	Expected wear and tear for its age, operates as expected
	3	Above average wear and tear for its age, still operates as expected
	2	Heavy wear, is operable but needs attention
	1	Requires repair(s) to function as expected
Exterior Rating	3 - Notable Wear - Fully Operable	
Interior Rating	4 - Expected Wear - Fully Operable	
Safety Rating	4 - Expected Wear - Fully Operable	
Quality Rating	4 - Expected Wear - Fully Operable	
Functionality Rating	4 - Expected Wear - Fully Operable	
Overall Rating	4 - Expected Wear - Fully Operable	
What's Great About the Machine	The great thing about this machine is that it does all its major functions and it is easy to assemble and disassemble	
What Needs Work	The thing that needs work on this trailer is the small rips and tears to the outer tarp system	
Date/Time	12-20-2024	
Inspector Name	Javier Bocanegra	