



## Inspection Report (Trailer)

### General Info

B&B Stock Number	A9936526
Year	2022
Make	EBY
Model	LP14k Trailer
Serial Number	4A2MB2020N3008339
Serial Plate Photo	

### Dimensions

Data Plate Photo	
Length (ft and inches)	82"
Width (ft and inches)	20"
Max Height (ft and inches)	0
Dock Height (ft and inches)	2'2"
GVWR (lbs)	14000
GAWR (lbs)	7000

### Features and Configuration

PTO Driven	No
Air Ride	No

## Inspection Report (Trailer)

Equipment Ramps	Yes
Tilt Deck	No
Dump Trailer	No
Deck Extension	No
Tarp System	No
Spare Tire	Yes
Winch	No
OMM (Operator & Maintenance Manual)	Yes

## Exterior 360 Walkaround

### 360 Walkaround & Operating Video

### Walkaround Photos & Operating Video

Exterior Walkaround Photos					
					

## Trailer Inspection Points

### Trailer Inspection Points

### General Appearance Photos

Overall Trailer & Underside Photos					
					
					
					

## Frame & Body

Frame & Deck Condition	5 - Very Light or Minimal Wear
------------------------	--------------------------------

## Inspection Report (Trailer)

Trailer Lights/Wiring (Stop, Tail, Turn)	5 - Very Light or Minimal Wear
Frame & Body Overall Rating	5 - Very Light or Minimal Wear

## Hitch

Hitch Type	Pintle
Strand Wear?	No
Drawbar appears structurally sound	Yes
Overall Hitch Condition	5 - Very Light or Minimal Wear









## Brake Components

Brake Type	Electric Brakes
Brake Controller	Yes
Wire Connections	5 - Very Light or Minimal Wear
Brake Shoe Thickness	70%
Emergency Brake/Break-Away Appearance	5 - Very Light or Minimal Wear
Brake Overall Rating	5 - Very Light or Minimal Wear

## Suspension

Suspension Overall Rating	5 - Very Light or Minimal Wear
---------------------------	--------------------------------

## Wheels & Tires

Tire Brand	Rainier St
Tire Size	ST235/80R16
Loose Lugs	No
Left Tires - Ratio Remaining	70%
Left Tire Photos	   
Right Tires - Ratio Remaining	70%
Right Tire Photos	   
Wheels & Hub Condition	5 - Very Light or Minimal Wear

## Hydraulics

Hydraulics Overall Rating	N/A
---------------------------	-----

## Functional Test

## Inspection Report (Trailer)

Brakes (visual)	5 - Very Light or Minimal Wear
Light System	5 - Very Light or Minimal Wear
Hydraulic Controls	N/A
Winch	N/A

## Inspection Summary

### Overall Assessment

Inspection Rating Criteria	Rating	Explanation
	5	Light or minimal wear for its age
	4	Expected wear and tear for its age, operates as expected
	3	Above average wear and tear for its age, still operates as expected
	2	Heavy wear, is operable but needs attention
	1	Requires repair(s) to function as expected
Exterior Rating	5 - Very Light or Minimal Wear	
Interior Rating	5 - Very Light or Minimal Wear	
Safety Rating	5 - Very Light or Minimal Wear	
Quality Rating	5 - Very Light or Minimal Wear	
Functionality Rating	5 - Very Light or Minimal Wear	
Overall Rating	5 - Very Light or Minimal Wear	
What's Great About the Machine	The great thing about this trailer is that it has light to minimal wear and tear	
What Needs Work	Na	
Date/Time	02-26-2025	
Inspector Name	Javier Bocanegra	
Assessment Details	<p>Boom &amp; Bucket provides an on-site visual inspection of the Unit. The inspection of mechanical components may be limited to starting and running the engine and basic hydraulic movements. Any operational tests are limited to low speeds and are not tested under load. The functionality of locking differentials, transmission shifting, all drive axels, brakes, and auxiliary or high flow hydraulics (unless required for an included attachment) cannot be fully verified. Additional information may be available on request. Please see the terms of services on our website for full details.</p>	