

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.


Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

Hydraulics

Item	Assessment	Photo
Excavator_2 #23		
Pumps (Hydraulics)	★★★★	
Valves	★★★★	
Hydraulic Tank	★★★★	
Hoses (Hydraulics)	★★★★	

Auxiliary Hydraulic Plumbing	Not operationally checked, End of stick	
Swing Motor	★★★★☆	
Hydraulic Center Swivel	★★★★☆	
Boom Swing Cylinders	★★★★☆	
Boom Lift Cylinder(s)	★★★★☆	
Stick Cylinder	★★★☆☆ Dripping leak	
Bucket Cylinder	★★★★☆	
Blade Lift Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	

Excavator_2 # 1		
Excavator_2 # 2		
Excavator_2 # 3		
Excavator_2 # 4		
Excavator_2 # 5		
Excavator_2 # 6		
Excavator_2 # 7		

Excavator_2 # 8		
Excavator_2 # 9		
Excavator_2 # 10		
Excavator_2 # 11		
Excavator_2 # 12		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Drivetrain #7		
Drivetrain #6		
Drivetrain #5		
Left Drive Motor	★★★★☆	
Right Drive Motor	★★★★☆	
Left Final Drive	★★★★☆	
Right Final Drive	★★★★☆	
Limited Function Check	The drivetrain was operational.	

Excavator General Appearance*

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		
Serial Number / VIN	CAT3035ELRKY04360	
Paint Condition**	Damage	


Body Panels*	No visible damage or missing components	
Steps``	No visible damage or missing components	
Hand Rails`	No visible damage or missing components	
Lights*	All lights operational	
Excavator* # 1		
Excavator* # 2		
Excavator* # 3		

Excavator* # 4		
Excavator* # 5		
Excavator* # 6		
Excavator* # 7		


Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Swing Brake	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	


Control Station - CE Excavator*		
Item	Assessment	Photo
Seat/Armrests*	Operator seat cushion damaged	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	No oil pressure indicator	
Fault Indicator Lights	Operational	

Gauges	Operational	
Hour Meter / Odometer	833 hrs	
Limited Function Check	The main components are in place and operational as noted.	
Excavator* # 1		
Excavator* # 2		
Excavator* # 3		

Engine - CE*		
Item	Assessment	Photo
Starter	Operational	
Exhaust System**	No visible damage or missing components	
Radiator	☆☆☆☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Limited Function Check	Belt makes a noise when you start it up	

Engine - CE* #1		 A close-up photograph of a yellow engine component, likely a hydraulic pump or valve, with a silver-colored circular cap. The component is mounted on a yellow frame. An "IRON PLANET" watermark is visible in the bottom right corner.
Engine - CE* #2		 A close-up photograph of a yellow engine component, showing a red hose and a black hose connected to a silver-colored metal part. An "IRON PLANET" watermark is visible in the bottom right corner.
Engine - CE* #3		 A close-up photograph of a yellow engine component, showing a yellow hose and a black hose connected to a silver-colored metal part. An "IRON PLANET" watermark is visible in the bottom right corner.
Engine - CE* #4		 A close-up photograph of a yellow engine component, showing a yellow hose and a black hose connected to a silver-colored metal part. An "IRON PLANET" watermark is visible in the bottom right corner.
Engine - CE* #5		 A close-up photograph of a yellow engine component, showing a yellow hose and a black hose connected to a silver-colored metal part. An "IRON PLANET" watermark is visible in the bottom right corner.
Engine - CE* #6		 A close-up photograph of a yellow engine component, showing a yellow hose and a black hose connected to a silver-colored metal part. An "IRON PLANET" watermark is visible in the bottom right corner.

Excavator Chassis*		
Item	Assessment	Photo
Boom Condition	★★★★☆	
Stick Condition	★★★★☆	
Swing Tower Pivot	★★★★☆	
Boom Base Pin and Bushings	★★★★☆	
Pin and Bushings Boom to Stick	★★★★☆	
Pin and Bushings Stick to Bucket	★★★★☆	

Turntable Bearing	★★★★☆	
Bottom Covers*	★★★★☆	
Limited Function Check	The main components were operational in a limited check.	
Excavator* # 1		
Excavator* # 2		
Excavator* # 3		
Excavator* # 4		
Excavator* # 5		


Excavator* # 6		
Excavator* # 7		

Undercarriage

Undercarriage components photos (links, bushings, sprockets, idlers, rollers, grouser) are selected as representative. Bidders are encouraged to review photos using the zoom feature to judge condition in detail.

Item	Assessment	Photo
Roller Frames	★★★★☆	
Grouser Height Measurement	Left side: 10 mm, Right side: 11 mm	
Track Belt Condition		
Rubber Belt Drive Lugs	No visible damage	
Track Tensioners	Operational	
Carrier Rollers		
Front Idler Wear		
Track Rollers		


Sprockets		
Undercarriage #1		
Undercarriage #2		
Undercarriage #3		
Undercarriage #4		
Undercarriage #5		
Undercarriage #6		

Undercarriage #7		
Undercarriage #8		
Undercarriage #9		
Undercarriage #10		
Undercarriage #11		
Undercarriage #12		
Undercarriage #13		

Undercarriage #14



Specialty - Excavator*		
Item	Assessment	Photo
Excavator Bucket Condition	★★★★☆	
Bucket Cutting Edge/Shanks/Teeth*	★★★★☆	
Blade Condition	★★★★☆	
Blade Cutting Edge Condition*		

Specialty		
Item	Assessment	Photo
Excavator_2 # 1		
Excavator_2 # 2		
Excavator_2 # 3		
Excavator_2 # 4		
Excavator_2 # 5		
Excavator_2 # 6		

Excavator_2 # 7		
Excavator_2 # 8		
Excavator_2 # 9		
Excavator_2 # 10		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved