

ABR-5000

Firmware Version 5.5.2 - Recommended Update

Note: As part of Luxul's ongoing improvements to product security, all new firmware updates will support cryptographic signatures. Implementing firmware signatures will enable Luxul to guarantee authenticity of the firmware update image.

Enhancements:

- Maintenance release with minor updates to the UI and other features.
- Improvements to the functionality of remote cloud connections.

Known Limitations:

- If using ProWatch, and have any SW-510/610 series switches connected to the network, the switch ports info will not display in the ProWatch app after updating to Firmware 5.5.0.
Solution: After the update, using the ProWatch app delete any SW-510/610 series switches from your sites and let ProWatch rediscover the switches. ProWatch will now will display the ports correctly.
- When using Safari on macOS, in some cases when changing the admin password you are not redirected to a new login screen.
Solution: Close the current tab/browser, open a new tab/browser session and browse to the new IP address of the device. This fixes the issue and will allow you to move forward.
- When using the CLI to set up the ABR-5000 from a factory default state, there is no way to enable the WAN ports because the CLI doesn't allow for the admin password to be changed. You will need to log in to the UI and change the admin password before the WAN ports will be enabled.

Firmware Version 5.5.1

Enhancements:

- Maintenance release with minor updates to the UI, security, and other features.
- Adds ProWatch support for upcoming new product releases.
- Improves efficiency of internet traffic.

Known Limitations:

- See above

Downloads

Current Version:

- [Firmware Version 5.5.2](#)

Previous Version:

- [Firmware Version 5.5.1](#)

For questions regarding previous firmware versions:

[contact support](#)