

XWR-1200

Release Firmware Version 6.9.0 - Recommended Update (Must update to FW 6.8.2 before applying this update)

Note: *It is NOT recommended to update the firmware wirelessly as damage to the router may occur.*

Note: *As part of Luxul's ongoing improvements to product security, all new firmware updates will support cryptographic signatures. Implementing firmware signatures will enable Luxul to guarantee authenticity of the firmware update image.*

Firmware versions on the XWR-1200 older than 6.8.2 must be updated to 6.8.2 before updating to the current release version.

Enhancements:

- Maintenance release with minor updates to the UI and other features.
- Improvements to the functionality of remote cloud connections.

Known Limitations:

- *When using Safari on macOS, in some cases when changing the admin password you are not redirected to a new login screen. **Solution:** Close the current tab/browser, open a new tab/browser session and browse to the new IP address of the device. This fixes the issue and will allow you to move forward.*

Release Firmware Version 6.8.2

Enhancements:

- DHCP page improvements
- Minor UI improvements and fixes
- Support for requiring signed firmware on future firmware updates

Known Limitations:

- *When using Safari on macOS, in some cases when changing the admin password you are not redirected to a new login screen. **Solution:** Close the current tab/browser, open a new tab/browser session and browse to the new IP address of the device. This fixes the issue and will allow you to move forward*

Downloads

Current Version:

- [Firmware Version 6.9.0](#)

Previous Version:

- [Firmware Version 6.8.2](#)

For questions regarding previous firmware versions:

[contact support](#)