



XAP-1230

Firmware Version 6.3.0 - Recommended Update

Note: It is NOT recommended to update the firmware wirelessly.

Enhancements:

- You will now not be required to do a reboot when making wireless settings / profile changes
- Corrected a subnet mask display error
- This update will provide support for future Wireless Controller updates
- Minor UI improvements

Firmware Version 6.1.3

Enhancements:

- OS and driver updates
- Minor UI improvements and bug fixes
- You will now be automatically notified in the user interface when a firmware update is available.

Firmware Version 5.0.5.2

Enhancements:

- KRACK vulnerability patch

Firmware Version 5.0.5

Enhancements:

- Allows the user to set a time zone on AP
- Allows the user to force the AP to find the controller if discovery process doesn't work
- Allows limited AP UI access when connected to controller
- Issues Resolved:
- Driver updates and bug fixes

Firmware Version 5.0.1

Enhancements:

Note: If you are not going to use your AP with a Luxul Wireless Controller you do not need to update the firmware.

Caution: It is not possible to downgrade the AP from firmware version 5, so upgrade only if you are certain you don't want to go back.

- Controller compatibility
- New look to the standalone AP UI

Note: You must restore the AP to factory default settings after upgrading the firmware from 4.X to 5.X firmware.

Downloads

- [Upgrade Instructions](#)

Current Version:

- [XAP-1230 Firmware Version 6.3.0](#)

Previous Version:

- [XAP-1230 Firmware Version 6.1.3](#)
- [XAP-1230 Firmware Version 5.0.5.2](#)
- [XAP-1230 Firmware Version 5.0.5](#)
- [XAP-1230 Firmware Version 5.0.1](#)

Configuration:

- [IP Addressing](#)
- [AP Factory Reset](#)

Firmware Version 4.0.3

Enhancements:

No enhancements included in this build

Issues Resolved:

- Kernel update providing up to date Ethernet and Wireless drivers for the hardware platform. This has resolved isolated instances of unstable data rates and/or device disconnect issues.

Firmware Version 4.0.2

Issues Resolved:

- Updated some help messages.
- Updated some language issues in the Web Interface

Enhancements:

No enhancements included in this build

Copyright and Trademark Notices

No part of this document may be modified or adapted in any way, for any purposes without permission in writing from Luxul. The material in this document is subject to change without notice. Luxul reserves the right to make changes to any product to improve reliability, function, or design. No license is granted, either expressly or by implication or otherwise under any Luxul intellectual property rights. An implied license only exists for equipment, circuits and subsystems contained in this or any Luxul product.

© Copyright 2020 Legrand AV Inc. All rights reserved. The name Luxul, the Luxul logo, the Luxul logo mark and Simply Connected are all trademarks and or registered trademarks of Legrand AV Inc.

All other trademarks and registered trademarks are property of their respective holders.

A brand of  legrand®