



XAP-1500

Release Firmware Version 6.3.0

Recommended Update

Note: It is NOT recommended to update the firmware wirelessly.

Enhancements:

- You will now not be required to do a reboot when making wireless settings / profile changes
- Corrected a subnet mask display error
- This update will provide support for future Wireless Controller updates
- Minor UI improvements

Firmware Version 6.1.3

Enhancements:

- OS and driver updates
- Minor UI improvements and bug fixes
- You will now be automatically notified in the user interface when a firmware update is available.

Firmware Version 5.0.5.2

Enhancements:

- KRACK vulnerability patch

Firmware Version 5.0.5

- Under certain conditions, APs running 5.0.3 may occasionally reboot or lock up. If you're using version 5.0.3, this is a critical upgrade.
- If you're using 5.0.2 no upgrade is required unless you would like to take advantage of some of the enhancements including increased Wi-Fi performance.
- If your APs are on 4x and you are not using a wireless controller, no upgrade is required.

Note: If any unexpected behavior occurs, we recommend you reset your access point to factory default.

Issues Resolved:

- Driver updates and minor bug fixes

Enhancements:

- Improved wireless throughput when used with the XWC-1000 Wireless Controller
- Improved stability
- Time zone can now be set on the AP
- Option for the AP to find the XWC-1000 Wireless Controller if not found during the automatic discovery process via the "Link Controller" feature in the "Administration" section.
- Offers limited user interface access to the AP when it is connected to the XWC-1000 Wireless Controller.

Downloads

- [Upgrade Instructions](#)

Current Version:

- [XAP-1500 Firmware Version 6.3.0](#)

Previous Version:

- [XAP-1500 Firmware Version 6.1.3](#)
- [XAP-1500 Firmware Version 5.0.5.2](#)
- [XAP-1500 Firmware Version 5.0.5](#)
- [XAP-1500 Firmware Version 5.0.2](#)

Configuration:

- [IP Addressing](#)
- [AP Factory Reset](#)

Firmware Version 5.0.2

Issues Resolved:

Note: You must restore the AP to factory default settings after upgrading this version firmware.

- Fixed the bug that allowed the stand alone Access Point UI to operate even while under control of the XWC-1000 controller. Prior to this bug fix, logging into the AP would disable controller communications and the controller would then show the AP as being offline.
- Minor bug fixes

Enhancements:

No enhancements included in this build

Firmware Version 5.0.1

Enhancements:

- Controller compatibility
- New look to the standalone AP UI

Firmware Version 4.0.3

Issues Resolved:

- A small number of XAP-1500's have exhibited issues when rebooting that can cause the device to stop broadcasting until the power is disconnected for 30-60 seconds and then reconnected.
- Updated some help messages.
- Updated some language issues in the Web Interface

Enhancements:

No enhancements included in this build

Copyright and Trademark Notices

No part of this document may be modified or adapted in any way, for any purposes without permission in writing from Luxul. The material in this document is subject to change without notice. Luxul reserves the right to make changes to any product to improve reliability, function, or design. No license is granted, either expressly or by implication or otherwise under any Luxul intellectual property rights. An implied license only exists for equipment, circuits and subsystems contained in this or any Luxul product.

© Copyright 2020 Legrand AV Inc. All rights reserved. The name Luxul, the Luxul logo, the Luxul logo mark and Simply Connected are all trademarks and or registered trademarks of Legrand AV Inc.

All other trademarks and registered trademarks are property of their respective holders.