


FIRMWARE V2.0 TROUBLESHOOTING GUIDE



If you encounter an error while installing firmware v2.0 or higher on your Select Series PDU with RackLink™, verify that your device is running firmware v1.16.04 before proceeding with the upgrade. Firmware v1.16.04 is available on the Legrand AV website at <https://www.legrandav.com/resources/power-downloads>.

If you encounter errors after installing firmware v2.0, try refreshing your web browser by pressing **Ctrl + F5** or **Ctrl + Fn + F5** (for Windows laptops) to ensure proper loading.

The firmware version can be found at the bottom of the dashboard



USA 866.977.3901 av.support@legrand.com
CANADA 877.345.4329 av.support@legrand.com
EMEA +31 495 580 840 av.emea.sales@legrand.com
APAC +852 2145 4099 av.asia.sales@legrand.com

C2G | CHIEF | DA-LITE | LUXUL | MIDDLE ATLANTIC | VADDIO | WIREMOLD

**MIDDLE
ATLANTIC**
A brand of **legrand**

©2025 Legrand AV Inc. 250379 Rev B 8/25 C2G, Chief, Da-Lite, Luxul, Middle Atlantic, Vaddio and Wiremold registered trademarks of Legrand AV Inc. All other brand names or marks are used for identification purposes and are trademarks of their respective owners. All patents are protected under existing designations. Other patents pending.