

Inspections: Damaged Pole Report

Service Request 25-00237190 Sector: Gateway Primary

Location on Service Request 6100 Moravia Park dr

Grid : 2020530 LLC: 7036

Descriptive Location and Comments:

Street: Moravia Park dr

Side of Street: N/S ☒ E/S ☐ S/S ☐ W/S ☐

Pole location: 1st ☐ 2nd ☒ 3rd ☐ 4th ☐ 5th ☐ 6th ☐ Other ☐

Direction : N/O ☐ E/O ☒ S/O ☐ W/O ☐

Street or Landmark: Frankford Ave

Condition of Pole:

Deteriorated ☒
Missing ☒
Damaged ☐
Arm/Fixture Missing ☐
Other ☐

Pole Size :

11'6" ☐
12' ☐
25' ☒
30' ☐
40' ☐
Other ☐

Type of Pole:

Aluminum ☒
Steel ☐
Galvanized Steel ☐
Fiberglass ☐
Bolton Hill ☐
Otterbein ☐
Homeland ☐
Wooden ☐
Other ☐

Fixture Type:

Cobra Head ☒
PMA ☐
Otterbein ☐
Homeland ☐
Bolton Hill ☐
Victorian Acorn ☐
Other ☐

Lamp Type:

HPS Vapor ☐
Mercury Vapor ☐
Metal Halide ☐
LED ☒
Other ☐

Wattage:

100 ☐
150 ☐
175 ☐
250 ☒
400 ☐
1000 ☐
Other ☐

Arm:

6' ☒
10' ☐
15' ☐
20' ☐
Other ☐

Arm Condition:

Damaged ☐
Missing ☒

Pedestal Base:

Yes ☐
No ☒


Base Condition:

Good ☒
Bad: ☐
Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal ☒
Concrete ☐

Date: 3/25/2025 Inspector's Signature: [Signature]



25 Foot Aluminum pole
cobra head
LED