

Inspections: Damaged Pole Report

Service Request: 25-00360246 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 4019 Frankford Ave

Grid : 2030410 LLC: 7203

Descriptive Location and Comments:

Street: Frankford Ave

Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ☒ W/O _____

Street or Landmark: Corse Ave

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' _____

25' ☒

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 ☒

400 _____

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing ☒

Pedestal Base:

Yes ☒

No _____

Base Condition:

Bolts ☒

Wires ☒

Conduit ☒

Good

☒

☒

☒

Bad:

☐

☐


☐

Base Type:

Metal ☒

Concrete _____

Date: 5/5/2025 Inspector's Signature: T. Blackman



25 Foot Aluminum pole
Cobra Head
LED