

Inspections: Damaged Pole Report

Service Request: 25-00360313 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 6603 PULASKI HWY

Grid : 2010510 LLC: 7029

Descriptive Location and Comments:

Street: PULASKI HWY

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: ROLYN AVE

Condition of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' _____
25' _____
30' ☒
40' _____
Other _____

Type of Pole:

Aluminum ☒
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

NEEDS
New Base

Fixture Type:

Cobra Head ☒
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ☒
Other _____

Wattage:

100 _____
150 _____
175 _____
200 _____
250 _____
400 ☒
1000 _____

Arm:

6' ☒
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing ☒

Pedestal Base:

Yes _____
No ☒


Base Condition:

Good ☒
Bad: _____
Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal _____
Concrete ☒

Date: 5/6/2025 Inspector's Signature: T. Blackman



30 Foot Aluminum pole
Cobra Head
LED