

Inspections: Damaged Pole Report

Service Request: 25-00471198 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 4422 Springwood Ave

Grid: 2040520 LLC: 7006

Descriptive Location and Comments:

Street: Springwood Ave

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction: N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Eunith Ave

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size:

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

NEEDS
New Base

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor _____

Metal Halide _____

LED _____

Other _____

Wattage:

100 ☒

150 _____

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒
No _____

Base Condition:

Bolts
Wires
Conduit


Good ☒

Bad: ☒

Base Type:

Metal ☒
Concrete _____

Date: 6/9/2025 Inspector's Signature: T. Blackman



PMA
HPS