

Inspections: Damaged Pole Report

Service Request: 25-00533555 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 5914 YORK RD

Grid : 2050110 LLC: G260

Descriptive Location and Comments:

Street: YORK RD

Side of Street: N/S _____ E/S _____ S/S _____ W/S ✓

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O ✓ E/O _____ S/O _____ W/O _____

Street or Landmark: E. BELVDERE AVE

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum _____

Missing ✓

12' ✓

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland ✓

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor _____

100 ✓

6' _____

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ✓

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn ✓

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:


Yes _____
No ✓

Bolts
Wires
Conduit

✓
✓
✓

Metal ✓
Concrete _____

Date: 6-26-25 Inspector's Signature: [Signature]



Homeland pole Acorn fixture