

Inspections: Damaged Pole Report

Service Request: 25-00547043 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 607 Somerset Rd

Grid : 1040130 LLC: 7101

Descriptive Location and Comments:

Street: Somerset Rd

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Roland Ave

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor _____

Metal Halide _____

LED _____

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No ☒

Base Condition:

Good

Bad:

Base Type:

Bolts

Wires

Conduit

☒

☒


☒

Metal

Concrete

☒

Date: 7/21/2025 Inspector's Signature: G. Crowder 8512



607 Somerset

1040130-1100
7101

Service Request Summary Report
25-00547043
Printed Date: Jul 2, 2025 - 3:27:58 PM

Type: BGE-StLight Pole Installation
Created By: citizen Site Guest User
Service Request Owner: BGE
Method Received: API
SLA Detail: 45 Business Days

SR #: 25-00547043
Priority: Standard
Status: Pending
Status Date: Jul 02, 2025 3:26:35 PM
Created Date: Jun 29, 2025 9:59:48 AM
Overdue on: Sep 01, 2025 4:07:35 PM
Closed on:

Location: 607 SOMERSET RD, Baltimore City, 21210
Location Details: There is a streetlight that is leaning towards the street. It appears the connections at the base have corroded so that it is no longer stable.
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Matthew Scott		mattrestine@gmail.com	+1 (

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		7/2/2025 3:26 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1040130
Assign inspector	LLC / POLE #	7101
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
---------	------------	--------------	------------