

Inspections: Damaged Pole Report

Service Request: 25-00556829 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1508 E. Madison St

Grid : 2010140 LLC: 6316

Descriptive Location and Comments:

Street: Madison St

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: No. Caroline

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum _____

Missing ☒

12' ☒

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland ☒

Wooden _____

Other _____

Work Order #
20259487

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor _____

100 _____

6' _____

Damaged _____

PMA _____

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ☒

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn ☒

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes _____
No ☒

Bolts _____
Wires ☒
Conduit ☒

Metal ☒
Concrete _____

Date: 7/7/2025 Inspector's Signature: T. Blackman



Home land
pole
Acorn Fixture