

Inspections: Damaged Pole Report

Service Request: 25-00550551 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 211 Eo Northern Pkwy

Grid : 1050120 LLC: 7263

Descriptive Location and Comments:

Street: Northern Pkwy

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Springlake way

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' _____

25' _____

30' ☒

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 _____

400 ☒

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing ☒

Pedestal Base:

Yes ☒
No _____

Base Condition:

Good _____

Bad: _____


Base Type:

Bolts ☒
Wires ☒
Conduit ☒

Metal _____
Concrete ☒

Date: 7/7/2025 Inspector's Signature: T. Blackman

NEEDS
New Base



30 Foot Aluminum
pole
Cobra Hired
LED