

Inspections: Damaged Pole Report

Service Request: 25-00576001 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 4600 ANN TANA Ave

Grid : 2030420 LLC: 7135

Descriptive Location and Comments:

Street: ANN TANA Ave

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Knell Ave

Condition of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" ☒
12' _____
25' _____
30' _____
40' _____
Other _____

Type of Pole:

Aluminum ☒
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

NEEDS
NEW BASE

Fixture Type:

Cobra Head ☒
PMA ☒
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide ☒
LED ☒
Other _____

Wattage:

100 _____
150 ☒
175 _____
200 _____
250 _____
400 _____
1000 _____

Arm:

6' _____
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes ☒
No _____

Base Condition:

Bolts ☒
Wires ☒
Conduit ☒

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
Concrete _____

Date: 7/10/2025 Inspector's Signature: T. Blackman



PMA
BLE
LED