

Inspections: Damaged Pole Report

Service Request 25-00596397 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 4700 Sinclair LN

Grid : 2020410 LLC: 7056

Descriptive Location and Comments:

Street: Sinclair LN

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th ☒ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Parkside dr

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' _____

25' ☒

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 _____

400 ☒

1000 _____

Arm:

5' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged ☒

Missing ☒

Pedestal Base:

Yes ☒
No ☒

Base Condition:

Bolts
Wires
Conduit

Good

☒
☒
☒

Bad:

Base Type:

Metal ☒
Concrete ☒

Date: 7/17/2025 Inspector's Signature: T. Blackman

