

Inspections: Damaged Pole Report

Service Request 25-00617922 Sector: _____ Gateway _____ Primary: _____

Location on Service Request: Eo PrattSt & S. ExeterSt

Grid : 4010140 LLC: 6389

Descriptive Location and Comments:

Street: PrattSt

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: S. ExeterSt

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum _____

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein ☒

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head _____

PMA _____

Otterbein ☒

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor _____

Metal Halide _____

LED _____

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes _____

No _____

Base Condition:

Good _____

Bad: _____

Base Type:

Bolts _____


Wires _____

Conduit _____

Metal _____

Concrete _____

Date: 7/24/2025 Inspector's Signature: T. Blackman



Otterbein
Pole
Otterbein
Fixtore