

Inspections: Damaged Pole Report

Service Request: 25-00670942 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3818 PULASKI HWY

Grid : 4010320 ILC: 6266

Descriptive Location and Comments:

Street: PULASKI HWY

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd _____ 3rd _____ 4th _____ 5th ☒ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: CONKLING ST

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated ☐

11'6" ☐

Aluminum ☐

Missing ☒

12' ☒

Steel ☐

Damaged ☐

25' ☐

Galvanized Steel ☐

Arm/Fixture Missing ☐

30' ☐

Fiberglass ☐

Other ☐

40' ☐

Bolton Hill ☐

Other ☐

Otterbein ☒

Homeland ☐

Wooden ☐

Other ☐

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☐

HPS Vapor ☒

100 ☐

6' ☐

Damaged ☐

PMA ☐

Mercury Vapor ☐

150 ☒

10' ☐

Missing ☐

Otterbein ☐

Metal Halide ☐

175 ☐

15' ☐

Homeland ☐

LED ☐

200 ☐

20' ☐

Bolton Hill ☐

Other ☐

250 ☐

Other ☐

Victorian Acorn ☒

400 ☐

Other ☐

1000 ☐

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes ☐
No ☒

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete ☐

Date: 8/7/2025 Inspector's Signature: T. Blackman



Otterbein
Acorn Fixture