

Inspections: Damaged Pole Report

Service Request: 25-00695450 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 6642 HOLABIRD AVE

Grid : 4020540 LLC: 5007

Descriptive Location and Comments:

Street: HOLABIRD AVE

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: DUNDALK AVE

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____	11'6" _____	Aluminum _____
Missing ☒	12' ☒	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland ☒
		Wooden _____
		Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____	HPS Vapor _____	100 _____	6' _____	Damaged _____
PMA _____	Mercury Vapor _____	150 ☒	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ☒	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn ☒		400 _____		
Other _____		1000 _____		

Pedestal Base:

Base Condition: Good

Bad:

Base Type:

Yes _____	Bolts ☒	Metal ☒
No ☒	Wires ☒	Concrete _____
	Conduit ☒	

Date: 8-13-25 Inspector's Signature: [Signature]



Report a Street Light Outage

Google Maps

DOT Richard Street - NEW

https://www.bjg.org/streetlights/public/default.html

Apps ArcGIS DOT Richard Street Moving Smart Street

6642 Holabird Ave

Working Light

Light Out - 2-11-15

Light Out - 1-1-15

Light Out - 1-1-15

Light Out - 1-1-15

Light Out - 1-1-15

Light Out - 1-1-15

Light Out - 1-1-15

Light Out - 1-1-15

Light Out - 1-1-15

Light Out - 1-1-15

Light Out - 1-1-15

4020540 5007