

Inspections: Damaged Pole Report

Service Request: 25-00693801 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 891 N. Howard St
 Grid : 1010140 ILC: 7921

Descriptive Location and Comments:

Street: Howard St
 Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
 Pole location: 1st _____ 2nd _____ 3rd ☒ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O ☒ W/O _____
 Street or Landmark: Read St

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' ☒
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum _____
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein ☒
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head _____
 PMA _____
 Otterbein ☒
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor ☒
 Mercury Vapor _____
 Metal Halide _____
 LED _____
 Other _____

Wattage:

100 _____
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No ☒

Base Condition:

Bolts
 Wires
 Conduit

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 8/15/2025 Inspector's Signature: T. Blackman



Ottenbetrn pole
Ottenbetrn
Fixture