

Inspections: Damaged Pole Report

Service Request: 25-00700794 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 5128 CHALgrove Ave

Grid : 1040420 LLC: 7044

Descriptive Location and Comments:

Street: CHALgrove Ave

Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ☒ W/O _____

Street or Landmark: W. Belvedere

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" ☒

Aluminum ☒

Missing ☒

12' _____

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

**NEEDS
New
BASE**

Other _____
**Work order #
20287102**

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒

HPS Vapor _____

100 _____

6' _____

Damaged _____

PMA ☒

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein _____

Metal Halide ☒

175 _____

15' _____

Homeland _____

LED ☒

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes _____
No ☒

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete _____

Date: 4 / 14 / 2025 Inspector's Signature: T. Blackman



PMIA
CCTV LED