

Inspections: Damaged Pole Report

Service Request: 25-00705361 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: No Robinson St & Pulaski Hwy
 Grid : 4010310 LLC: 6260

Descriptive Location and Comments:

Street: Pulaski Hwy
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: Robinson St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

11'6" _____
 12' ☒
 25' _____
 30' _____
 40' _____
 Other _____

Aluminum _____
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein ☒
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn ☒
 Other _____

HPS Vapor ☒
 Mercury Vapor _____
 Metal Halide _____
 LED _____
 Other _____

100 _____
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Damaged _____
 Missing _____

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes _____
 No ☒

Bolts ☒
 Wires ☒
 Conduit ☒

Metal ☒
 Concrete _____

Date: 8/19/2025 Inspector's Signature: T. Blackman



Otterbein
Acorn Fixture