

Inspections: Damaged Pole Report

Service Request: 25-00704901 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 4217 OAK Ford Ave
 Grid : 1030520 LLC: 7041

Descriptive Location and Comments:

Street: OAK Ford Ave
 Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
 Pole location: 1st _____ 2nd _____ 3rd ☒ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: Hillsdale Rd

Condition of Pole:

Deteriorated ☒

Missing _____

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum _____

Steel ☒

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide ☒

LED ☒

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes _____
 No ☒

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good

☒
☒
☒


Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 1 / 1 2025 Inspector's Signature: T. Blackman

NEEDS
 NEW
 BASE



Steel PMA
CITY LED