

Inspections: Damaged Pole Report

Service Request: 25-00709503 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 502 N. Chapel Gate LN

Grid : 3010530 LLC: 7085

Descriptive Location and Comments:

Street: Chapel Gate LN

Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O ☒ E/O _____ S/O _____ W/O _____

Street or Landmark: Woodside Rd

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum _____

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland ☒

Wooden _____

Other _____

Work order #
20247476

Fixture Type:

Cobra Head _____

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn ☒

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide ☒

LED ☒

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No _____

Base Condition:

Good

Bad:

Base Type:

Bolts

Wires

Conduit

☒

☒


☒

Metal

Concrete

☒

Date: 4/20/2025 Inspector's Signature: T. Blackman



Home landscape
Acorn Fixture