

Inspections: Damaged Pole Report

Service Request 25-06707237 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 3412 Woodberry Ave
 Grid : 1030230 LLC: 6309

Descriptive Location and Comments:

Street: Woodberry Ave
 Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
 Pole location: 1st _____ 2nd _____ 3rd _____ 4th _____ 5th ☒ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O ☒ W/O _____
 Street or Landmark: Eric Shaefer way

Condition of Pole:

Deteriorated _____

Missing _____

Damaged ☒

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor _____

Metal Halide _____

LED _____

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No ☒

Base Condition:

Bolts
Wires
Conduit

Good

☒

☒

☒


Bad:

Base Type:

Metal ☒

Concrete _____

Date: 8/20/2025 Inspector's Signature: T. Blackman



PMA
HPS