

Inspections: Damaged Pole Report

already ~ Bot Sign

WO# 20382389

Service Request: 25-00730451 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 3200 Reisterstown Rd
 Grid : 1020 320 LLC: 7078

Descriptive Location and Comments:

Street: Reisterstown Rd
 Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O ☒ E/O _____ S/O _____ W/O _____
 Street or Landmark: Chowan Ave

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum ☒

Missing ☒

12' _____

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' ☒

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒

HPS Vapor _____

100 _____

6' ☒

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ☒

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 ☒

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes ☒
No ☒

Bolts
Wires
Conduit

☒
☒
☒

Metal ☒
Concrete ☒

Date: 8 / 25 / 2025 Inspector's Signature: G. Crowder 8512

30 ft cat
LEAD

