

Inspections: Damaged Pole Report

Service Request 25-00746470 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 423 E. Hamburg St

Grid : 4020110 LLC: 7043

Descriptive Location and Comments:

Street: Hamburg St

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1" _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: River Side Ave

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' _____

25' ☒

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes _____
No _____


Base Condition: Good _____ Bad _____

Bolts _____
Wires _____
Conduit _____

Base Type:

Metal _____
Concrete _____

Date: 8 / 30 / 2025 Inspector's Signature: T. Blackman



25 Foot
Aluminum pole
cobra head
LED