

Inspections: Damaged Pole Report

Service Request 25-00748066 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1434 Bonsai St

Grid : 4020420 LLC: 7022

Descriptive Location and Comments:

Street: Bonsai St

Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O ☒ E/O _____ S/O _____ W/O _____

Street or Landmark: Cardiff Ave

Condition of Pole:

Deteriorated ☒
Missing _____
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" ☒
12' _____
25' _____
30' _____
40' _____
Other _____

Type of Pole:

Aluminum _____
Steel ☒
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

NEeds
New Base

Fixture Type:

Cobra Head _____
PMA ☒
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor ☒
Mercury Vapor _____
Metal Halide _____
LED _____
Other _____

Wattage:

100 _____
150 ☒
175 _____
200 _____
250 _____
400 _____
1000 _____

Arm:

6' _____
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes _____
No ☒

Base Condition:

Good ☒
Bad: _____
Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal ☒
Concrete _____

Date: 9/3/2025 Inspector's Signature: T. Blackman


25-00748066 Service Request Report a Street Light Outage

bge.streetlightoutages.com/public/default.html

Apps Arc Gis DOT Richard Stevas Moving Smart Enter

1436 bonsal st ballimore

bge



Steel
PMA
HPS