

Inspections: Damaged Pole Report

Service Request: 25-00825801 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 3400 PULASKI HWY
 Grid : 4010310 LLC: 6270

Descriptive Location and Comments:

Street: PULASKI HWY
 Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
 Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: Highland Ave

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated ☒

11'6" ☒

Aluminum _____

Missing ☒

12' ☒

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein ☒

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor _____

100 _____

6' _____

Damaged _____

PMA _____

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein _____

Metal Halide ☒

175 _____

15' _____

Homeland _____

LED ☒

200 _____

20' _____

Bolton Hill ☒

Other _____

250 _____

Other _____

Victorian Acorn ☒

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes _____
 No ☒

Bolts _____
 Wires ☒
 Conduit ☒

Metal _____
 Concrete ☒

Date: 9/25/2025 Inspector's Signature: T. Blackman



Often been
Acorn Fixture