

Inspections: Damaged Pole Report

Service Request: 25-00846073 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 700 S. Robinson St
 Grid : 4010330 LLC: 7462

Descriptive Location and Comments:

Street: S. Robinson St
 Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O ☒ W/O _____
 Street or Landmark: Footer Ave

Condition of Pole:

Deteriorated ☒
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" ☒
 12' _____
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head ☒
 PMA ☒
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide ☒
 LED ☒
 Other _____

Wattage:

100 ☒
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No ☒

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good

☒
☒
☒


Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 10/3/2025 Inspector's Signature: T. Blackman

NEEDS
NEW
BASE



PMA
City LED