

Inspections: Damaged Pole Report

Service Request: 25-00853284 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 6011 Pinehurst Rd

Grid : 2050110 LLC: 7057

Descriptive Location and Comments:

Street: Pinehurst Rd

Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ☒ W/O _____

Street or Landmark: Melrose Ave

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" ☒

Aluminum ☒

Missing ☒

12' _____

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

**NEEDS
NEW BASE**

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒

HPS Vapor ☒

100 ☒

6' _____

Damaged _____

PMA ☒

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED _____

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes ☒
No _____

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete _____

Date: 10/7/2025 Inspector's Signature: T. Blackman



PMIA
HPS