

# Inspections: Damaged Pole Report

Service Request 25-00870379 Sector \_\_\_\_\_ Gateway \_\_\_\_\_ Primary \_\_\_\_\_  
 Location on Service Request: 7. E. North Ave  
 Grid : 1010120 LLC: 6293

## Descriptive Location and Comments:

Street: E. North Ave  
 Side of Street: N/S \_\_\_\_\_ E/S \_\_\_\_\_ S/S ☒ W/S \_\_\_\_\_  
 Pole location: 1<sup>st</sup> \_\_\_\_\_ 2<sup>nd</sup> ☒ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_  
 Direction : N/O \_\_\_\_\_ E/O ☒ S/O \_\_\_\_\_ W/O \_\_\_\_\_  
 Street or Landmark: Charles St

## Condition of Pole:

Deteriorated \_\_\_\_\_  
 Missing ☒  
 Damaged \_\_\_\_\_  
 Arm/Fixture Missing \_\_\_\_\_  
 Other \_\_\_\_\_

## Pole Size :

11'6" \_\_\_\_\_  
 12' ☒  
 25' \_\_\_\_\_  
 30' \_\_\_\_\_  
 40' \_\_\_\_\_  
 Other \_\_\_\_\_

## Type of Pole:

Aluminum \_\_\_\_\_  
 Steel \_\_\_\_\_  
 Galvanized Steel \_\_\_\_\_  
 Fiberglass \_\_\_\_\_  
 Bolton Hill \_\_\_\_\_  
 Otterbein \_\_\_\_\_  
 Homeland ☒  
 Wooden \_\_\_\_\_  
 Other \_\_\_\_\_

## Fixture Type:

Cobra Head \_\_\_\_\_  
 PMA \_\_\_\_\_  
 Otterbein \_\_\_\_\_  
 Homeland \_\_\_\_\_  
 Bolton Hill \_\_\_\_\_  
 Victorian Acorn ☒  
 Other \_\_\_\_\_

## Lamp Type:

HPS Vapor \_\_\_\_\_  
 Mercury Vapor \_\_\_\_\_  
 Metal Halide \_\_\_\_\_  
 LED ☒  
 Other \_\_\_\_\_

## Wattage:

100 \_\_\_\_\_  
 150 ☒  
 175 \_\_\_\_\_  
 200 \_\_\_\_\_  
 250 \_\_\_\_\_  
 400 \_\_\_\_\_  
 1000 \_\_\_\_\_

## Arm:

6' \_\_\_\_\_  
 10' \_\_\_\_\_  
 15' \_\_\_\_\_  
 20' \_\_\_\_\_  
 Other \_\_\_\_\_

## Arm Condition:

Damaged \_\_\_\_\_  
 Missing \_\_\_\_\_

## Pedestal Base:

Yes \_\_\_\_\_  
 No ☒

## Base Condition:

Bolts \_\_\_\_\_  
 Wires \_\_\_\_\_  
 Conduit \_\_\_\_\_

## Good

☒  
☒  
☒


## Bad:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

## Base Type:

Metal ☒  
 Concrete \_\_\_\_\_

Date: 10/9/2025 Inspector's Signature: T. Blackman



Home land  
Acorn Fixture