

# Inspections Damaged Pole Report

Service Request 25-00889447 Sector Gateway Primary           
 Location on Service Request: 3123 Dillon St  
 Grid : 4020310 LLC: 7292

## Descriptive Location and Comments:


Street: Dillon St  
 Side of Street: N/S          E/S          S/S ✓ W/S           
 Pole location: 1<sup>st</sup> ✓ 2<sup>nd</sup>          3<sup>rd</sup>          4<sup>th</sup>          5<sup>th</sup>          6<sup>th</sup>          Other           
 Direction : N/O          E/O ✓ S/O          W/O           
 Street or Landmark: So Robinson St

| Condition of Pole:                  | Pole Size :           | Type of Pole:                    |
|-------------------------------------|-----------------------|----------------------------------|
| Deteriorated <u>        </u>        | 11'6" <u>        </u> | Aluminum <u>✓</u>                |
| Missing <u>✓</u>                    | 12' <u>        </u>   | Steel <u>        </u>            |
| Damaged <u>        </u>             | 25' <u>✓</u>          | Galvanized Steel <u>        </u> |
| Arm/Fixture Missing <u>        </u> | 30' <u>        </u>   | Fiberglass <u>        </u>       |
| Other <u>        </u>               | 40' <u>        </u>   | Bolton Hill <u>        </u>      |
|                                     | Other <u>        </u> | Otterbein <u>        </u>        |
|                                     |                       | Homeland <u>        </u>         |
|                                     |                       | Wooden <u>        </u>           |
|                                     |                       | Other <u>        </u>            |

| Fixture Type:                   | Lamp Type:                    | Wattage:             | Arm:                  | Arm Condition:          |
|---------------------------------|-------------------------------|----------------------|-----------------------|-------------------------|
| Cobra Head <u>✓</u>             | HPS Vapor <u>        </u>     | 100 <u>        </u>  | 6' <u>✓</u>           | Damaged <u>        </u> |
| PMA <u>        </u>             | Mercury Vapor <u>        </u> | 150 <u>        </u>  | 10' <u>        </u>   | Missing <u>✓</u>        |
| Otterbein <u>        </u>       | Metal Halide <u>        </u>  | 175 <u>        </u>  | 15' <u>        </u>   |                         |
| Homeland <u>        </u>        | LED <u>✓</u>                  | 200 <u>        </u>  | 20' <u>        </u>   |                         |
| Bolton Hill <u>        </u>     | Other <u>        </u>         | 250 <u>✓</u>         | Other <u>        </u> |                         |
| Victorian Acorn <u>        </u> |                               | 400 <u>        </u>  |                       |                         |
| Other <u>        </u>           |                               | 1000 <u>        </u> |                       |                         |

| Pedestal Base:     | Base Condition:  | Good            | Bad:            | Base Type:               |
|--------------------|------------------|-----------------|-----------------|--------------------------|
| Yes <u>✓</u>       | Bolts <u>✓</u>   | <u>        </u> | <u>        </u> | Metal <u>✓</u>           |
| No <u>        </u> | Wires <u>✓</u>   | <u>        </u> | <u>        </u> | Concrete <u>        </u> |
|                    | Conduit <u>✓</u> | <u>        </u> | <u>        </u> |                          |

Date: 10/17/2025 Inspector's Signature: T. Blackman



25 Foot Aluminum  
pole  
COBRA HEAD  
LED