

Inspections Damaged Pole Report

Service Request 25-00889490 Sector Gateway Primary:

Location on Service Request: 3201 Dillon St

Grid : 4020310 LLC: 7047

Descriptive Location and Comments:

Street: Dillon St

Side of Street: N/S E/S S/S ✓ W/S

Pole location: 1" ✓ 2nd 3rd 4th 5th 6th Other

Direction : N/O E/O ✓ S/O W/O

Street or Landmark: So East Ave

Condition of Pole:

Deteriorated
Missing ✓
Damaged
Arm/Fixture Missing
Other

Pole Size :

11'6"
12'
25' ✓
30'
40'
Other

Type of Pole:

Aluminum ✓
Steel
Galvanized Steel
Fiberglass
Bolton Hill
Otterbein
Homeland
Wooden
Other

Fixture Type:

Cobra Head ✓
PMA
Otterbein
Homeland
Bolton Hill
Victorian Acorn
Other

Lamp Type:

HPS Vapor
Mercury Vapor
Metal Halide
LED ✓
Other

Wattage:

100
150
175
200
250 ✓
400
1000

Arm:

6' ✓
10'
15'
20'
Other

Arm Condition:

Damaged
Missing ✓

Pedestal Base:

Yes
No ✓

Base Condition:

Bolts
Wires
Conduit

Good

✓
✓
✓

Bad:

Base Type:

Metal
Concrete

Date: 10/17/2025 Inspector's Signature T. Blackman

